


0005

COPY

C/007/035 Incoming
CC: Karl



Sunnyside Cogeneration Associates

#3515
K

P.O. Box 10, East Carbon, Utah 84520 • (435) 888-4476 • Fax (435) 888-2538

March 23, 2010

Daron Haddock
Division of Oil, Gas & Mining
1594 W. North Temple, Suite 1210
Salt Lake City, Utah 84116

RE: Annual Report for 2009
SCA Sunnyside Mining Permit, C/007/035

Dear Mr. Haddock:

Please find enclosed two copies of SCA's Annual report for 2009, for coal mining and reclamation operations at the SCA Sunnyside site. This report is inclusive of the activities that occurred within the SCA Sunnyside Mining Permit area during 2009.

Should you have any questions, please contact Rusty Netz or myself at (435)888-4476.

Thank You,

Richard Carter
Agent For
Sunnyside Cogeneration Associates

cc. Steve Gross
William Rossiter
Maggie Estrada
Paul Shepard
Rusty Netz
Plant File

File in:


☐ Confidential
☒ Shelf
☐ Expandable

Refer to Record No. 0005, Date 03232010
In C/007/035 2010 Incoming
For additional information

RECEIVED

MAR 29 2010

DIV. OF OIL, GAS & MINING



2009 Annual Report

Sunnyside Cogeneration Associates
Sunnyside Refuse and Slurry
C/007/035





**SUNNYSIDE COGENERATION ASSOCIATES
SUNNYSIDE REFUSE/SLURRY
C/007/0035
2009 ANNUAL REPORT**

Submitted to:


State of Utah
Department of Natural Resources
Division of Oil, Gas and Mining
1594 West North Temple, Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801



SUNNYSIDE COGENERATION ASSOCIATES
SUNNYSIDE REFUSE/SLURRY
2009 ANNUAL REPORT

TABLE OF CONTENTS

- I. General Permit Information:**
- II. Identification of Other Permits**
- III. Certified Reports**
- IV. Reporting of Other Technical Data**
 - 1. Climatological Data
 - 2. Subsidence Monitoring Data
 - 3. Vegetation Monitoring Data
 - 4. Raptor Surveys and Wildlife Programs
 - 5. Water Monitoring Data
 - 6. Geological / Geophysical Data
 - 7. Engineering Data (Refuse Excavation and Spoils Disposal)
 - 8. Soils Monitoring Data
 - 9. Other Data
- V. Legal, Financial, Compliance and Related Information**
 - Certificates of Existence from the Department of Commerce
- VI. Mine Maps**
- Appendix A Certified Reports**
- Appendix B-1 Climatological Data**
- Appendix B-2 Water Monitoring**
- Appendix C Dept of Commerce, Certificates of Existence**
- Appendix D Mine Map**



I. GENERAL PERMIT INFORMATION

Permit Number: C/007/0035

Mine Name: Sunnyside Refuse/Slurry

Permittee: Sunnyside Cogeneration Associates

**Company Representative
& Resident Agent:** Mr. Richard Carter
One Power Plant Road
PO Box 159
Sunnyside, UT 84539
(435) 888-4476
(435) 888-2538 fax

Date of Initial Permanent Program Permit: February 4, 1993

Date of Most Recent Permit Renewal: February 4, 2008

Date of Expiration: February 4, 2013

SCA plans to complete the reclamation bond renewal process in 2010.



II. IDENTIFICATION OF OTHER PERMITS


MSHA ID Numbers:

Sunnyside Waste Coal Site	42-02093
Coarse Refuse Pile	1211-UT-09-02093-01
Excess Spoil Disposal Area #1	1211-UT-09-02093-04
Excess Spoil Disposal Area #2	1211-UT-09-02093-05

UPDES Permit Number: UT0024759 Renewed effective August 1, 2007
Expires July 31, 2012

Air Quality Title V Operating Permit: #700030001

SCA renewed its Title V permit in 2007. Most of the emissions are associated with the power plant adjacent to the SCA Sunnyside mining permit area. The mining operation generates little to no emissions. However the Operating Permit covers all of SCA's operations in Sunnyside.



III. CERTIFIED REPORTS


Each impoundment as well as the Refuse Pile and Excess Spoil Disposal Areas was inspected in accordance with the requirements of the Mining and Reclamation Permit. The quarterly and annual inspection / certification reports were submitted to the Division throughout the year. These reports are also included in **Appendix A**.

All of the impoundments met or exceeded the storage capacity requirements identified in the permit. No discharges occurred from any of the impoundments during 2009.

All of the spoils materials and coal reject materials generated during 2009 were placed in the Excess Spoil Disposal Area #2. No new materials were placed in the Excess Spoil Disposal Area #1. Construction is progressing in general conformance with design requirements as currently approved.

SCA gathered soil samples from the Excess Spoil Disposal Area #2 during 2009. The analytical test results have not yet been received from the lab so they will be reported with the 2010 quarterly inspection reports.

Excavation of Coarse and Fine Refuse from the Refuse Pile occurred in general conformance with the operational criteria and performance standards established in the permit.



IV. REPORTING OF OTHER TECHNICAL DATA

1. Climatological Data

SCA has obtained precipitation and climatological data for 2009 from the Sunnyside Weather Station operated by the City of Sunnyside. A summary table identifying this data is included in **Appendix B-1**.

2. Subsidence Monitoring Data


No subsidence monitoring is required by the approved plan. No material damage or diminution within the Permit Area will be caused by subsidence because no underground coal resources are available within the permit area that would cause subsidence. No past or future underground coal mining operations have or are likely to occur within the SCA Permit Area.

3. Vegetation Monitoring Data

During 2009, no new areas received final reclamation treatment. In an effort to perform contemporaneous reclamation, SCA is committed to reclaim areas of two acres or larger that are permanently excavated of waste, and are no longer needed for the continued operations. There are currently no areas that meet these criteria.

In 2007, SCA performed quantitative sampling of the Old Coarse Refuse Road that was reclaimed in 1994. This sampling was conducted with the anticipation that SCA could submit an application for Final Phase III Bond Release with the 2006 data set being used as "Year 1" and the 2007 data set as "Year 2" of the two consecutive years of vegetation monitoring necessary to apply for bond release. SCA has not yet filed the paperwork necessary to request final bond release. No additional sampling is required for this area.

Interim reseeding has been performed in previous years on several areas throughout the permit site. This interim seeding was accomplished using the approved interim seed mix included in the permit. These areas previously reseeded with the interim revegetation seed mix have been periodically checked by SCA and appear to have vegetative growth similar to the surrounding area.



4. Raptor Surveys and Wildlife Programs

Discussions were held in 1998 with the Division concerning whether or not raptor surveys would be needed. Both the permittee and the Division have agreed that, considering the location of the permit site and the ongoing nature of SCA's activities, it is highly unlikely that the mining and reclamation activities of SCA would negatively affect raptor nesting sites. Therefore, raptor studies would have little value and are not required by the approved permit. Hence, no raptor studies have been performed.


SCA is committed to carrying out its operations in a manner that minimizes potential impact on wildlife in the area. These operations are centered on excavation and hauling activities in and around the coal pile and storage areas. These operations continue to be performed in a manner that does not prevent the necessary migration of large mammals. No additional efforts have been requested by DOGM to provide for migration routes.

SCA also provides periodic wildlife awareness training during employee staff meetings to educate employees associated with the site activities regarding the values of the wildlife resources in the local area. Employee training advises against unnecessary harassment or taking of wildlife on site.

5. Water Monitoring Data

As required in the approved plan, SCA performed quarterly water monitoring at the specified surface and ground water monitoring locations. These sites were analyzed according to the Operational Water Quality Monitoring Parameters listed in the MRP (Appendix 7-8). SCA has prepared an analysis of the water quality obtained during the period 2003-2008 for comparison with the data obtained during the 1993-1995 Baseline Monitoring Period and the 1996-2002 Operational Monitoring Period. The results of these analyses indicate that the water quality has remained in general similarity to that observed during the prior monitoring periods. This analysis report was included in Appendix B-4 of the 2009 Annual Report. A summary of the 1993-1995 Baseline water quality data is included in the MRP as Appendix 7-4. A summary of the 1996-2002 Operational water quality data is included in the MRP as Appendix 7-10.

The 2009 water data from each of the quarterly monitoring periods was submitted to the Division throughout the year. An additional copy of the data has been included in **Appendix B-3** of this report.



6. Geological / Geophysical Data

No periodic Geological / Geophysical monitoring is required in the approved plan. The data included as resource information in the plan is considered adequate for the operations of SCA. In the event that the operations of SCA change dramatically such that additional geologic or geophysical data becomes necessary, additional analysis will be performed at that time.

7. Engineering Data

a. Refuse Excavation

During 2009, SCA excavated 189,191 tons from the Sunnyside permit area. Of that, 65,564 tons was rejected to the Excess Spoil Disposal Area #2 and 123,617 tons was burned. The Sunnyside facility also received 271,325 tons from the Star Point facility;

b. Excess Spoils Disposal Area #1

No new material was placed in this disposal area during 2009.

c. Excess Spoil Disposal Area #2

Placement and compaction of fill material occurred in this disposal area throughout 2009. Materials placed in the disposal area consist mostly of coarse refuse rejects, but also include some general spoils material. Approximately 65,564 tons of material were placed in this disposal area during 2009. (1st qtr – 11,519; 2nd qtr – 20,130; 3rd qtr – 17,640; 4th qtr – 16,275 tons). Material samples were taken towards the end of 2009. Lab analysis of these samples will be provided with the quarterly inspections in 2010.

Inspections of the refuse area and both spoils areas are conducted on a quarterly basis. Reports from these site visits are submitted to the Division throughout the year and have been included in this report with the certified reports.




8. Soils Monitoring Data

No periodic soil monitoring is required by the approved plan. The approved borrow areas reserved for reclamation activities have previously undergone soils studies from which the data is included in Chapter 2 of the Permit.

In the event that SCA determines it necessary to utilize soils from other sources for reclamation, the proper analysis will be performed at that time.

9. Other Data

No additional periodic data is required in the approved plan.



V. LEGAL, FINANCIAL, COMPLIANCE & RELATED INFORMATION

Sunnyside Cogeneration Associates is a joint venture between Sunnyside Holdings I, Inc. and Sunnyside II, L.P. **Appendix C** includes copies of the Certificates of Existence for Sunnyside Cogeneration Associates, Sunnyside Holdings I, Inc. and Sunnyside II, L.P. The Utah Department of Commerce, Division of Corporations and Commercial Code issues these certificates. They demonstrate that the entities are in good standing with the State of Utah.




VI. MINE MAPS


The mine map included in **Appendix D** of this report includes recent site contours and a photograph showing the surface configuration of the refuse area being excavated. This refuse is then utilized as fuel for the adjacent Cogeneration Facility. The aerial survey used to generate contours of the site was performed in April 2007.

Mining excavation of the refuse pile has occurred in general conformance with the approved mining plan.

Mining activity proposed for the next five years is projected to occur in general conformance with the mining plan shown on the PE Certified drawings approved in the Mining and Reclamation Permit.




APPENDIX A CERTIFIED REPORTS



APPENDIX A CERTIFIED REPORTS

FIRST QUARTER INSPECTION

IMPOUNDMENTS, REFUSE PILE AND DISPOSAL AREAS



Sunnyside Cogeneration Associates

P.O. Box 10, East Carbon, Utah 84520 • (435) 888-4476 • Fax (435) 888-2538

April 28, 2009

Daron Haddock
Utah Division of Oil, Gas & Mining
1594 W. North Temple, Suite 1210
Salt Lake City, Utah 84116


RE: First Quarter 2009 Inspection Report
Sunnyside Refuse Pile C/007/035

Dear Daron:

Please find enclosed a copy of the First Quarter 2009 Inspection Report for Sunnyside Cogeneration Associates' impoundments, refuse pile and excess spoil areas.

Should you have any questions, please contact Rusty Netz or myself at (435)888-4476.

Thank You,



Michael J. Blakey

Agent For
Sunnyside Cogeneration Associates

c.c. Steve Gross
William Rossiter
Paul Shepard
Maggie Estrada
Rusty Netz
Plant File

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

GENERAL INFORMATION

Railcut Sediment Pond

Report Date April 20, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name RailCut Sediment Pond
Impoundment Number 007
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date March 19, 2009
Inspected by Rusty Netz
Reason for Inspection First Quarter Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 4.8 Acre-feet
Pond bottom elevation = 6206.0
100% Sediment Storage Volume = 0.34 acre-feet at Elevation 6209
60% sediment Storage Volume = 0.2 acre feet at Elevation = 6207.7
Existing Sediment Elevation = 6207.0 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6209.07
Emergency Spillway Elevation = 6212.34

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond had no water in it. No samples were taken Pond did not require decanting
Sediment levels were good
Embankment conditions were good. Vegetation on out slopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Rail Cut Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure have been observed

No water was impounded

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty not

Date: _____

4/28/09

CERTIFIED REPORT IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |


COMMENTS/ OTHER INFORMATION

None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Old Coarse Refuse Road Sediment Pond

GENERAL INFORMATION

Report Date April 20, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name Old Coarse Refuse Road Sediment Pond
Impoundment Number 008
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date March 19, 2009
Inspected by Rusty Netz
Reason for Inspection First Quarter Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 0.9 Acre-feet
Pond bottom elevation = 6394.0
100% Sediment Storage Volume = 0.08 acre-feet at Elevation 6395.1
60% sediment Storage Volume = 0.05 acre feet at Elevation = 6394.75
Existing Sediment Elevation = 6394.25 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6395.75
Emergency Spillway Elevation = 6399.4

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond had no water in it. No samples were taken Pond did not require decanting.
Sediment level was good.
Embankment conditions were good. Vegetation on out slopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Old Coarse Refuse Road Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure have been observed

No water was impounded

Sediment level was good.

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: Rusty ref

Date: 4/28/09

CERTIFIED REPORT IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |


COMMENTS/ OTHER INFORMATION

None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Pasture Sediment Pond

GENERAL INFORMATION

Report Date April 20, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name Pasture Sediment Pond
Impoundment Number 009
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date March 19, 2009
Inspected by Rusty Netz
Reason for Inspection First Quarter Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 3.2 Acre-feet
Pond bottom elevation = 6484.5
100% Sediment Storage Volume = 0.42 acre-feet at Elevation 6486.2
60% sediment Storage Volume = 0.25 acre feet at Elevation = 6485.5
Existing Sediment Elevation = 6485.0 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6486.6
Emergency Spillway Elevation = 6490.6

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond had some water in it. No samples were taken Pond did not require decanting.
Sediment level was good
Embankment conditions were good. Vegetation on out slopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Pasture Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure were observed.

A small amount of water was impounded

Sediment level was good.

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty Rety

Date: _____

4/28/09

CERTIFIED REPORT IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |


COMMENTS/ OTHER INFORMATION

None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Coarse Refuse Toe Sediment Pond

GENERAL INFORMATION

Report Date April 20, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name New Coarse Refuse Toe Sediment Pond
Impoundment Number 012
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date March 19, 2009
Inspected by Rusty Netz
Reason for Inspection First Quarter Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 1.6 Acre-feet
Pond bottom elevation = 6176.0
100% Sediment Storage Volume = 0.07 acre-feet at Elevation 6177.8
60% sediment Storage Volume = 0.03 acre feet at Elevation = 6177.0
Existing Sediment Elevation = 6176.5 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6178.2
Emergency Spillway Elevation = 6183.63

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond had no water in it. No samples were taken Pond did not require decanting
Sediment level was good
Embankment conditions were good. Vegetation on out slopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Coarse Refuse Toe Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure have been observed

No water was impounded

Sediment level was good.

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty nety

Date: _____

4/28/09

CERTIFIED REPORT

IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |


COMMENTS/ OTHER INFORMATION

None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

GENERAL INFORMATION

Coal Pile Sediment Pond

Report Date April 20, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name Coal Pile Sediment Pond
Impoundment Number 014
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date March 19, 2009
Inspected by Rusty Netz
Reason for Inspection First Quarter Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 1.5 Acre-feet
Pond bottom elevation = 6473.0
100% Sediment Storage Volume = 0.5 acre-feet at Elevation 6476.0
60% sediment Storage Volume = 0.3 acre feet at Elevation = 6474.7
Existing Sediment Elevation = 6473.8 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6476.0
Secondary Dewatering Orifice = 6477.2
Primary Spillway Elevation = 6477.9
Emergency Spillway Elevation = 6479.0

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond had some water in it. No samples were taken Pond did not require decanting.
Sediment level was good.
Embankment conditions were good. Vegetation on out slopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Coal Pile Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure have been observed

A small amount of water was impounded

Sediment level was good.

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty ref

Date: _____

4/28/09

CERTIFIED REPORT

IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |


COMMENTS/ OTHER INFORMATION

None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Borrow Area Sediment Pond

GENERAL INFORMATION

Report Date April 20, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name Borrow Area Sediment Pond
Impoundment Number 016
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date March 19, 2009
Inspected by Rusty Netz
Reason for Inspection First Quarter Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 8.3 Acre-feet
Pond bottom elevation = 6510.0
100% Sediment Storage Volume = 2.3 acre-feet at Elevation 6514.3
60% sediment Storage Volume = 1.4 acre feet at Elevation = 6513.3
Existing Sediment Elevation = 6511 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6514.3
Emergency Spillway Elevation = 6517.03

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond had no water in it. No samples were taken
Sediment level was good. Pond did not require decanting.
Embankment conditions were good. Vegetation on out slopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Borrow Area Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure have been observed

No water was impounded

Sediment level was good.

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty noty

Date: _____

4/28/09

CERTIFIED REPORT

IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |


COMMENTS/ OTHER INFORMATION

None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

GENERAL INFORMATION

Coarse Refuse Pile

Report Date April 20, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

EXCESS SPOIL PILE OR REFUSE PILE IDENTIFICATION

File Name Coarse Refuse Pile
File Number N/A
MSHA ID Number 1211-UT-09-02093-01

Inspection Date March 19, 2009
Inspected by Rusty Netz
Reason for Inspection First Quarter Inspection 2009

Attachment to Report? (such as refuse sample analysis or photos)

NO

Field Evaluation

1. Foundation preparation, including the removal of all organic material and topsoil.

N/A

2. Placement of underdrains and protective filter systems.

N/A

3. Installation of final surface drainage systems

N/A

4. Placement and compaction of fill materials

N/A - Activities occurring at this time are associated with removal of refuse material

5. Final grading and revegetation of fill.

N/A

6. Appearances of instability, structural weakness, and other hazardous conditions

No aspects of the Fill structure were observed that could affect its stability or functionality

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

Coarse Refuse Pile

7. Other comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period

Refuse material is actively being excavated and removed from various locations across the top of the pile

The Fast Slurry Cell has been decommissioned and the coal refuse material stored therein has been incorporated as part of the Coarse Refuse Pile.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty Rety

Date: _____

4/28/09

CERTIFICATION STATEMENT

I hereby certify that: I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with the approved design and meets or exceeds the minimum design requirements under all applicable federal, state, and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH

Affix Signature, Stamp and Date



INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

GENERAL INFORMATION

Excess Spoil Disposal Area #1

Report Date April 20, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

EXCESS SPOIL PILE OR REFUSE PILE IDENTIFICATION

File Name Excess Spoil Disposal Area #1
File Number N/A
MSHA ID Number 1211-UT-09-02093-04

Inspection Date March 19, 2009
Inspected by Rusty Netz
Reason for Inspection First Quarter Inspection 2009

Attachment to Report? (such as refuse sample analysis or photos) **NO**

Field Evaluation

1. Foundation preparation, including the removal of all organic material and topsoil.

N/A

2. Placement of underdrains and protective filter systems.

N/A

3. Installation of final surface drainage systems

N/A

4. Placement and compaction of fill materials

No new material was placed during the quarter.

5. Final grading and revegetation of fill.

N/A

6. Appearances of instability, structural weakness, and other hazardous conditions

No aspects of the Fill structure were observed that could affect its stability or functionality

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

Excess Spoil Disposal Area #1

7. Other comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period

Construction of the fill has been proceeding in shallow lifts in general conformance with the approved plan.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.


Signature: Rusty Rety Date: 4/28/09

CERTIFICATION STATEMENT

I hereby certify that: I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with the approved design and meets or exceeds the minimum design requirements under all applicable federal, state, and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH

Affix Signature, Stamp and Date



INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

GENERAL INFORMATION

Excess Spoil Disposal Area #2

Report Date April 20, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

EXCESS SPOIL PILE OR REFUSE PILE IDENTIFICATION

Pile Name Excess Spoil Disposal Area #2
Pile Number N/A
MSHA ID Number 1211-UT-09-02093-05

Inspection Date March 19, 2009
Inspected by Rusty Netz
Reason for Inspection First Quarter Inspection 2009

Attachment to Report? (such as refuse sample analysis or photos) **NO**

Field Evaluation

1. Foundation preparation, including the removal of all organic material and topsoil.

Existing disturbed site. No additional topsoil removal is required by the approved plan

2. Placement of underdrains and protective filter systems.

No under-drains or filters area required by the approved plan

3. Installation of final surface drainage systems

N/A

4. Placement and compaction of fill materials

Approximately 11,519 tons of material were placed in this disposal area during the quarter.

5. Final grading and revegetation of fill.

N/A

6. Appearances of instability, structural weakness, and other hazardous conditions

No aspects of the Fill structure were observed that could affect its stability or functionality

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

Excess Spoil Disposal Area #2

7. Other comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period

Both Slurry Ponds 1 & 2 have now been filled. The Clear Water Pond has been included within this Disposal Area. SCA has completed an enlargement of the Pasture Pond and has decommissioned the Clear Water Pond and incorporated the area within this Disposal Area. They can also continue filling the disposal area to the height approved.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.


Signature: Rusty nety Date: 4/28/09

CERTIFICATION STATEMENT

I hereby certify that: I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with the approved design and meets or exceeds the minimum design requirements under all applicable federal, state, and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH

Affix Signature, Stamp and Date






APPENDIX A CERTIFIED REPORTS

SECOND QUARTER INSPECTION

IMPOUNDMENTS, REFUSE PILE AND DISPOSAL AREAS



Sunnyside Cogeneration Associates

P.O. Box 10, East Carbon, Utah 84520 • (435) 888-4476 • Fax (435) 888-2538

July 24, 2009

Daron Haddock
Utah Division of Oil, Gas & Mining
1594 W. North Temple, Suite 1210
Salt Lake City, Utah 84116

RE: Second Quarter 2009 Inspection Report
Sunnyside Refuse Pile C/007/035

Dear Daron:

Please find enclosed a copy of the Second Quarter 2009 Inspection Report for Sunnyside Cogeneration Associates' impoundments, refuse pile and excess spoil areas.

Should you have any questions, please contact Rusty Netz or myself at (435)888-4476.

Thank You,

Richard Carter
Agent For
Sunnyside Cogeneration Associates

c.c. Steve Gross
William Rossiter
Paul Shepard
Maggie Estrada
Rusty Netz
Plant File

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

GENERAL INFORMATION

Railcut Sediment Pond

Report Date July 20, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name RailCut Sediment Pond
Impoundment Number 007
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date June 25, 2009
Inspected by Rusty Netz
Reason for Inspection Second Quarter Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 4.8 Acre-feet
Pond bottom elevation = 6206.0
100% Sediment Storage Volume = 0.34 acre-feet at Elevation 6209
60% sediment Storage Volume = 0.2 acre feet at Elevation = 6207.7
Existing Sediment Elevation = 6207.1 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6209.07
Emergency Spillway Elevation = 6212.34

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond had no water in it. No samples were taken Pond did not require decanting
Sediment levels were good
Embankment conditions were good. Vegetation on out slopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Rail Cut Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure have been observed

No water was impounded

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty Nety

Date: _____

7/24/09

CERTIFIED REPORT IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |

COMMENTS/ OTHER INFORMATION


None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH

Affix Signature, Stamp and Date



IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Old Coarse Refuse Road Sediment Pond

GENERAL INFORMATION

Report Date July 20, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name Old Coarse Refuse Road Sediment Pond
Impoundment Number 008
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date June 25, 2009
Inspected by Rusty Netz
Reason for Inspection Second Quarter Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 0.9 Acre-feet
Pond bottom elevation = 6394.0
100% Sediment Storage Volume = 0.08 acre-feet at Elevation 6395.1
60% sediment Storage Volume = 0.05 acre feet at Elevation = 6394.75
Existing Sediment Elevation = 6394.3 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6395.75
Emergency Spillway Elevation = 6399.4

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond had no water in it. No samples were taken Pond did not require decanting.
Sediment level was good.
Embankment conditions were good. Vegetation on out slopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Old Coarse Refuse Road Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure have been observed

No water was impounded

Sediment level was good.

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty net

Date: _____

7/24/09

CERTIFIED REPORT

IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |

COMMENTS/ OTHER INFORMATION

None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Pasture Sediment Pond

GENERAL INFORMATION

Report Date July 20, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name Pasture Sediment Pond
Impoundment Number 009
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date June 25, 2009
Inspected by Rusty Netz
Reason for Inspection Second Quarter Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 3.2 Acre-feet
Pond bottom elevation = 6484.5
100% Sediment Storage Volume = 0.42 acre-feet at Elevation 6486.2
60% sediment Storage Volume = 0.25 acre feet at Elevation = 6485.5
Existing Sediment Elevation = 6485.1 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6486.6
Emergency Spillway Elevation = 6490.6

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond had some water in it. No samples were taken Pond did not require decanting.
Sediment level was good
Embankment conditions were good. Vegetation on out slopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Pasture Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure were observed.

A small amount of water was impounded

Sediment level was good.

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: Rusty noty Date: 7/24/09

CERTIFIED REPORT IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |


COMMENTS/ OTHER INFORMATION

None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Coarse Refuse Toe Sediment Pond

GENERAL INFORMATION

Report Date July 20, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name New Coarse Refuse Toe Sediment Pond
Impoundment Number 012
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date June 25, 2009
Inspected by Rusty Netz
Reason for Inspection Second Quarter Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 1.6 Acre-feet
Pond bottom elevation = 6176.0
100% Sediment Storage Volume = 0.07 acre-feet at Elevation 6177.8
60% sediment Storage Volume = 0.03 acre feet at Elevation = 6177.0
Existing Sediment Elevation = 6176.5 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6178.2
Emergency Spillway Elevation = 6183.63

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond had no water in it. No samples were taken Pond did not require decanting
Sediment level was good
Embankment conditions were good. Vegetation on out slopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Coarse Refuse Toe Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure have been observed

No water was impounded

Sediment level was good.

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty nety

Date: _____

7/24/09

CERTIFIED REPORT

IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |


COMMENTS/ OTHER INFORMATION

None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

GENERAL INFORMATION

Coal Pile Sediment Pond

Report Date July 20, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name Coal Pile Sediment Pond
Impoundment Number 014
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date June 25, 2009
Inspected by Rusty Netz
Reason for Inspection Second Quarter Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 1.5 Acre-feet
Pond bottom elevation = 6473.0
100% Sediment Storage Volume = 0.5 acre-feet at Elevation 6476.0
60% sediment Storage Volume = 0.3 acre feet at Elevation = 6474.7
Existing Sediment Elevation = 6473.9 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6476.0
Secondary Dewatering Orifice = 6477.2
Primary Spillway Elevation = 6477.9
Emergency Spillway Elevation = 6479.0

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond had some water in it. No samples were taken Pond did not require decanting.
Sediment level was good.
Embankment conditions were good. Vegetation on out slopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Coal Pile Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure have been observed

A small amount of water was impounded

Sediment level was good.

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty Neth

Date: _____

7/24/09

CERTIFIED REPORT

IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |


COMMENTS/ OTHER INFORMATION

None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Borrow Area Sediment Pond

GENERAL INFORMATION

Report Date July 20, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name Borrow Area Sediment Pond
Impoundment Number 016
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date June 25, 2009
Inspected by Rusty Netz
Reason for Inspection Second Quarter Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 8.3 Acre-feet
Pond bottom elevation = 6510.0
100% Sediment Storage Volume = 2.3 acre-feet at Elevation 6514.3
60% sediment Storage Volume = 1.4 acre feet at Elevation = 6513.3
Existing Sediment Elevation = 6511 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6514.3
Emergency Spillway Elevation = 6517.03

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on outslopes of embankments, etc.

Pond had no water in it. No samples were taken
Sediment level was good. Pond did not require decanting.
Embankment conditions were good. Vegetation on outslopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Borrow Area Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure have been observed

No water was impounded

Sediment level was good.

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty nety

Date: _____

7/24/09

CERTIFIED REPORT

IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |


COMMENTS/ OTHER INFORMATION

None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

GENERAL INFORMATION

Coarse Refuse Pile

Report Date July 20, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

EXCESS SPOIL PILE OR REFUSE PILE IDENTIFICATION

Pile Name Coarse Refuse Pile
Pile Number N/A
MSHA ID Number 1211-UT-09-02093-01

Inspection Date June 25, 2009
Inspected by Rusty Netz
Reason for Inspection Second Quarter Inspection 2009

Attachment to Report? (such as refuse sample analysis or photos) **NO**

Field Evaluation

1. Foundation preparation, including the removal of all organic material and topsoil.

N/A

2. Placement of underdrains and protective filter systems.

N/A

3. Installation of final surface drainage systems

N/A

4. Placement and compaction of fill materials

N/A - Activities occurring at this time are associated with removal of refuse material

5. Final grading and revegetation of fill.

N/A

6. Appearances of instability, structural weakness, and other hazardous conditions

No aspects of the Fill structure were observed that could affect its stability or functionality

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

Coarse Refuse Pile

7. Other comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period

Refuse material is actively being excavated and removed from various locations across the top of the pile

The East Slurry Cell has been decommissioned and the coal refuse material stored therein has been incorporated as part of the Coarse Refuse Pile.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty net

Date: _____


7/24/09

CERTIFICATION STATEMENT

I hereby certify that: I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with the approved design and meets or exceeds the minimum design requirements under all applicable federal, state, and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH

Affix Signature, Stamp and Date



INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

GENERAL INFORMATION

Excess Spoil Disposal Area #1

Report Date July 20, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

EXCESS SPOIL PILE OR REFUSE PILE IDENTIFICATION

Pile Name Excess Spoil Disposal Area #1
Pile Number N/A
MSHA ID Number 1211-UT-09-02093-04

Inspection Date June 25, 2009
Inspected by Rusty Netz
Reason for Inspection Second Quarter Inspection 2009

Attachment to Report? (such as refuse sample analysis or photos) **NO**

Field Evaluation

1. Foundation preparation, including the removal of all organic material and topsoil.

N/A

2. Placement of underdrains and protective filter systems.

N/A

3. Installation of final surface drainage systems

N/A

4. Placement and compaction of fill materials

No new material was placed during the quarter.

5. Final grading and revegetation of fill.

N/A

6. Appearances of instability, structural weakness, and other hazardous conditions

No aspects of the Fill structure were observed that could affect its stability or functionality

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

Excess Spoil Disposal Area #1

7. Other comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period

Construction of the fill has been proceeding in shallow lifts in general conformance with the approved plan.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.


Signature: Ruey ref Date: 7/24/09

CERTIFICATION STATEMENT

I hereby certify that: I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with the approved design and meets or exceeds the minimum design requirements under all applicable federal, state, and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH

Affix Signature, Stamp and Date



INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

GENERAL INFORMATION

Excess Spoil Disposal Area #2

Report Date July 20, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

EXCESS SPOIL PILE OR REFUSE PILE IDENTIFICATION

File Name Excess Spoil Disposal Area #2
File Number N/A
MSHA ID Number 1211-UT-09-02093-05

Inspection Date June 25, 2009
Inspected by Rusty Netz
Reason for Inspection Second Quarter Inspection 2009

Attachment to Report? (such as refuse sample analysis or photos) **NO**

Field Evaluation

1. Foundation preparation, including the removal of all organic material and topsoil.

Existing disturbed site. No additional topsoil removal is required by the approved plan

2. Placement of underdrains and protective filter systems.

No under-drains or filters area required by the approved plan

3. Installation of final surface drainage systems

N/A

4. Placement and compaction of fill materials

Approximately 20,130 tons of material were placed in this disposal area during the quarter.

5. Final grading and revegetation of fill.

N/A

6. Appearances of instability, structural weakness, and other hazardous conditions

No aspects of the Fill structure were observed that could affect its stability or functionality

**INSPECTION AND CERTIFIED REPORT
ON EXCESS SPOIL PILE OR REFUSE PILE**

Excess Spoil Disposal Area #2

7. Other comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period

Both Slurry Ponds 1 & 2 have now been filled. The Clear Water Pond has been included within this Disposal Area. SCA has completed an enlargement of the Pasture Pond and has decommissioned the Clear Water Pond and incorporated the area within this Disposal Area. They can also continue filling the disposal area to the height approved.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty Ritz


Date: _____

7/24/09


CERTIFICATION STATEMENT

I hereby certify that: I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with the approved design and meets or exceeds the minimum design requirements under all applicable federal, state, and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH




Affix Signature, Stamp and Date



APPENDIX A CERTIFIED REPORTS

THIRD QUARTER INSPECTION

IMPOUNDMENTS, REFUSE PILE AND DISPOSAL AREAS



Sunnyside Cogeneration Associates

P.O. Box 10, East Carbon, Utah 84520 • (435) 888-4476 • Fax (435) 888-2538

October 16, 2009

Daron Haddock
Utah Division of Oil, Gas & Mining
1594 W. North Temple, Suite 1210
Salt Lake City, Utah 84116

RE: Third Quarter 2009 Inspection Report
Sunnyside Refuse Pile C/007/035

Dear Daron:

Please find enclosed a copy of the Third Quarter 2009 Inspection Report for Sunnyside Cogeneration Associates' impoundments, refuse pile and excess spoil areas.

Should you have any questions, please contact Rusty Netz or myself at (435)888-4476.

Thank You,

Richard Carter
Agent For
Sunnyside Cogeneration Associates

c.c. Steve Gross
William Rossiter
Paul Shepard
Maggie Estrada
Rusty Netz
Plant File

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

GENERAL INFORMATION

Railcut Sediment Pond

Report Date October 7, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name RailCut Sediment Pond
Impoundment Number 007
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date September 17, 2009
Inspected by Rusty Netz
Reason for Inspection Third Quarter Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 4.8 Acre-feet
Pond bottom elevation = 6206.0
100% Sediment Storage Volume = 0.34 acre-feet at Elevation 6209
60% sediment Storage Volume = 0.2 acre feet at Elevation = 6207.7
Existing Sediment Elevation = 6207.1 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6209.07
Emergency Spillway Elevation = 6212.34

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond had some water in it. No samples were taken Pond did not require decanting
Sediment levels were good
Embankment conditions were good. Vegetation on out slopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Rail Cut Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure have been observed

Some water was impounded

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: Rusty ref Date: 10/16/09

CERTIFIED REPORT IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |


COMMENTS/ OTHER INFORMATION

None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Old Coarse Refuse Road Sediment Pond

GENERAL INFORMATION

Report Date October 7, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name Old Coarse Refuse Road Sediment Pond
Impoundment Number 008
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date September 17, 2009
Inspected by Rusty Netz
Reason for Inspection Third Quarter Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 0.9 Acre-feet
Pond bottom elevation = 6394.0
100% Sediment Storage Volume = 0.08 acre-feet at Elevation 6395.1
60% sediment Storage Volume = 0.05 acre feet at Elevation = 6394.75
Existing Sediment Elevation = 6394.3 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6395.75
Emergency Spillway Elevation = 6399.4

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on outslopes of embankments, etc.

Pond had some water in it. No samples were taken Pond did not require decanting.
Sediment level was good.
Embankment conditions were good. Vegetation on outslopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Old Coarse Refuse Road Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure have been observed

Some water was impounded

Sediment level was good.

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty net

Date: _____

10/16/09

CERTIFIED REPORT

IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |


COMMENTS/ OTHER INFORMATION

None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Pasture Sediment Pond

GENERAL INFORMATION

Report Date October 7, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name Pasture Sediment Pond
Impoundment Number 009
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date September 17, 2009
Inspected by Rusty Netz
Reason for Inspection Third Quarter Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 3.2 Acre-feet
Pond bottom elevation = 6484.5
100% Sediment Storage Volume = 0.42 acre-feet at Elevation 6486.2
60% sediment Storage Volume = 0.25 acre feet at Elevation = 6485.5
Existing Sediment Elevation = 6485.1 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6486.6
Emergency Spillway Elevation = 6490.6

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond had some water in it. No samples were taken Pond did not require decanting.
Sediment level was good
Embankment conditions were good. Vegetation on out slopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Pasture Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure were observed.

A small amount of water was impounded

Sediment level was good.

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty not

Date: _____

10/16/09

CERTIFIED REPORT IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

1. Is impoundment designed and constructed in accordance with the approved plan? YES
2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? YES
3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? YES


COMMENTS/ OTHER INFORMATION

None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Coarse Refuse Toe Sediment Pond

GENERAL INFORMATION

Report Date October 7, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name New Coarse Refuse Toe Sediment Pond
Impoundment Number 012
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date September 17, 2009
Inspected by Rusty Netz
Reason for Inspection Third Quarter Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 1.6 Acre-feet
Pond bottom elevation = 6176.0
100% Sediment Storage Volume = 0.07 acre-feet at Elevation 6177.8
60% sediment Storage Volume = 0.03 acre feet at Elevation = 6177.0
Existing Sediment Elevation = 6176.5 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6178.2
Emergency Spillway Elevation = 6183.63

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on outslopes of embankments, etc.

Pond had some water in it. No samples were taken Pond did not require decanting
Sediment level was good
Embankment conditions were good. Vegetation on outslopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Coarse Refuse Toe Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure have been observed

Some water was impounded

Sediment level was good.

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty net

Date: _____

10/16/09

CERTIFIED REPORT

IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

1. Is impoundment designed and constructed in accordance with the approved plan? YES
2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? YES
3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? YES

COMMENTS/ OTHER INFORMATION


None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.

P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

GENERAL INFORMATION

Coal Pile Sediment Pond

Report Date October 7, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name Coal Pile Sediment Pond
Impoundment Number 014
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date September 17, 2009
Inspected by Rusty Netz
Reason for Inspection Third Quarter Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 1.5 Acre-feet
Pond bottom elevation = 6473.0
100% Sediment Storage Volume = 0.5 acre-feet at Elevation 6476.0
60% sediment Storage Volume = 0.3 acre feet at Elevation = 6474.7
Existing Sediment Elevation = 6473.9 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6476.0
Secondary Dewatering Orifice = 6477.2
Primary Spillway Elevation = 6477.9
Emergency Spillway Elevation = 6479.0

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond had some water in it. No samples were taken Pond did not require decanting.
Sediment level was good.
Embankment conditions were good. Vegetation on out slopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Coal Pile Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure have been observed

A small amount of water was impounded

Sediment level was good.

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty nd

Date: _____

10/16/09

CERTIFIED REPORT

IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

1. Is impoundment designed and constructed in accordance with the approved plan? YES
2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? YES
3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? YES


COMMENTS/ OTHER INFORMATION

None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Borrow Area Sediment Pond

GENERAL INFORMATION

Report Date October 7, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name Borrow Area Sediment Pond
Impoundment Number 016
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date September 17, 2009
Inspected by Rusty Netz
Reason for Inspection Third Quarter Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 8.3 Acre-feet
Pond bottom elevation = 6510.0
100% Sediment Storage Volume = 2.3 acre-feet at Elevation 6514.3
60% sediment Storage Volume = 1.4 acre feet at Elevation = 6513.3
Existing Sediment Elevation = 6511 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6514.3
Emergency Spillway Elevation = 6517.03

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond had no water in it. No samples were taken
Sediment level was good. Pond did not require decanting.
Embankment conditions were good. Vegetation on out slopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Borrow Area Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure have been observed

No water was impounded

Sediment level was good.

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty not

Date: _____

10/16/09

CERTIFIED REPORT IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |

COMMENTS/ OTHER INFORMATION


None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.

P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

GENERAL INFORMATION

Coarse Refuse Pile

Report Date October 7, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

EXCESS SPOIL PILE OR REFUSE PILE IDENTIFICATION

Pile Name Coarse Refuse Pile
Pile Number N/A
MSHA ID Number 1211-UT-09-02093-01

Inspection Date September 17, 2009
Inspected by Rusty Netz
Reason for Inspection Third Quarter Inspection 2009

Attachment to Report? (such as refuse sample analysis or photos) **NO**

Field Evaluation

1. Foundation preparation, including the removal of all organic material and topsoil.

N/A

2. Placement of underdrains and protective filter systems.

N/A

3. Installation of final surface drainage systems

N/A

4. Placement and compaction of fill materials

N/A - Activities occurring at this time are associated with removal of refuse material

5. Final grading and revegetation of fill.

N/A

6. Appearances of instability, structural weakness, and other hazardous conditions

No aspects of the Fill structure were observed that could affect its stability or functionality

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

Coarse Refuse Pile

7. Other comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period

Refuse material is actively being excavated and removed from various locations across the top of the pile

The East Slurry Cell has been decommissioned and the coal refuse material stored therein has been incorporated as part of the Coarse Refuse Pile.

QUALIFICATION STATEMENT:


I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: Rusty n.f. Date: 10/16/09

CERTIFICATION STATEMENT

I hereby certify that: I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with the approved design and meets or exceeds the minimum design requirements under all applicable federal, state, and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

GENERAL INFORMATION

Excess Spoil Disposal Area #1

Report Date October 7, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

EXCESS SPOIL PILE OR REFUSE PILE IDENTIFICATION

Pile Name Excess Spoil Disposal Area #1
Pile Number N/A
MSHA ID Number 1211-UT-09-02093-04

Inspection Date September 17, 2009
Inspected by Rusty Netz
Reason for Inspection Third Quarter Inspection 2009

Attachment to Report? (such as refuse sample analysis or photos) **NO**

Field Evaluation

1. Foundation preparation, including the removal of all organic material and topsoil.

N/A

2. Placement of underdrains and protective filter systems.

N/A

3. Installation of final surface drainage systems

N/A

4. Placement and compaction of fill materials

No new material was placed during the quarter.

5. Final grading and revegetation of fill.

N/A

6. Appearances of instability, structural weakness, and other hazardous conditions

No aspects of the Fill structure were observed that could affect its stability or functionality

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

Excess Spoil Disposal Area #1

7. Other comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period

Construction of the fill has been proceeding in shallow lifts in general conformance with the approved plan.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.


Signature: Rusty net Date: 10/14/09

CERTIFICATION STATEMENT

I hereby certify that: I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with the approved design and meets or exceeds the minimum design requirements under all applicable federal, state, and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH

Affix Signature, Stamp and Date



INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

GENERAL INFORMATION

Excess Spoil Disposal Area #2

Report Date October 7, 2009
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

EXCESS SPOIL PILE OR REFUSE PILE IDENTIFICATION

Pile Name Excess Spoil Disposal Area #2
Pile Number N/A
MSHA ID Number 1211-UT-09-02093-05

Inspection Date September 17, 2009
Inspected by Rusty Netz
Reason for Inspection Third Quarter Inspection 2009

Attachment to Report? (such as refuse sample analysis or photos) **NO**

Field Evaluation

1. Foundation preparation, including the removal of all organic material and topsoil.

Existing disturbed site. No additional topsoil removal is required by the approved plan

2. Placement of underdrains and protective filter systems.

No under-drains or filters area required by the approved plan

3. Installation of final surface drainage systems

N/A

4. Placement and compaction of fill materials

Approximately 17,640 tons of material were placed in this disposal area during the quarter.

5. Final grading and revegetation of fill.

N/A

6. Appearances of instability, structural weakness, and other hazardous conditions

No aspects of the Fill structure were observed that could affect its stability or functionality

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

Excess Spoil Disposal Area #2

7. Other comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period

Both Slurry Ponds 1 & 2 have now been filled. The Clear Water Pond has been included within this Disposal Area. SCA has completed an enlargement of the Pasture Pond and has decommissioned the Clear Water Pond and incorporated the area within this Disposal Area. They can also continue filling the disposal area to the height approved.

QUALIFICATION STATEMENT:


I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: Rusty net Date: 10/16/09


CERTIFICATION STATEMENT

I hereby certify that: I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with the approved design and meets or exceeds the minimum design requirements under all applicable federal, state, and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH




Affix Signature, Stamp and Date



APPENDIX A CERTIFIED REPORTS

FOURTH QUARTER INSPECTION

IMPOUNDMENTS, REFUSE PILE AND DISPOSAL AREAS



Sunnyside Cogeneration Associates

P.O. Box 10, East Carbon, Utah 84520 • (435) 888-4476 • Fax (435) 888-2538

January 15, 2010

Daron Haddock
Utah Division of Oil, Gas & Mining
1594 W. North Temple, Suite 1210
Salt Lake City, Utah 84116

RE: Fourth Quarter 2009 Inspection Report
Sunnyside Refuse Pile C/007/035

Dear Daron:

Please find enclosed a copy of the Fourth Quarter 2009 Inspection Report for Sunnyside Cogeneration Associates' impoundments, refuse pile and excess spoil areas.

Should you have any questions, please contact Rusty Netz or myself at (435)888-4476.

Thank You,

Richard Carter
Agent For
Sunnyside Cogeneration Associates

c.c. Steve Gross
William Rossiter
Paul Shepard
Maggie Estrada
Rusty Netz
Plant File

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

GENERAL INFORMATION

Railcut Sediment Pond

Report Date January 12, 2010
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name RailCut Sediment Pond
Impoundment Number 007
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date December 17, 2009
Inspected by Rusty Netz
Reason for Inspection Fourth Quarter Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 4.8 Acre-feet
Pond bottom elevation = 6206.0
100% Sediment Storage Volume = 0.34 acre-feet at Elevation 6209
60% sediment Storage Volume = 0.2 acre feet at Elevation = 6207.7
Existing Sediment Elevation = 6207.2 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6209.07
Emergency Spillway Elevation = 6212.34

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond had some water in it. No samples were taken Pond did not require decanting
Sediment levels were good
Embankment conditions were good. Vegetation on out slopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Rail Cut Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure have been observed

Some water was impounded

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty not

Date: _____

1/15/10

CERTIFIED REPORT IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |

COMMENTS/ OTHER INFORMATION


None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH

Affix Signature, Stamp and Date



IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Old Coarse Refuse Road Sediment Pond

GENERAL INFORMATION

Report Date January 12, 2010
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name Old Coarse Refuse Road Sediment Pond
Impoundment Number 008
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date December 17, 2009
Inspected by Rusty Netz
Reason for Inspection Fourth Quarter Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 0.9 Acre-feet
Pond bottom elevation = 6394.0
100% Sediment Storage Volume = 0.08 acre-feet at Elevation 6395.1
60% sediment Storage Volume = 0.05 acre feet at Elevation = 6394.75
Existing Sediment Elevation = 6394.4 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6395.75
Emergency Spillway Elevation = 6399.4

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond had some water in it. No samples were taken Pond did not require decanting.
Sediment level was good.
Embankment conditions were good. Vegetation on out slopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Old Coarse Refuse Road Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure have been observed

Some water was impounded

Sediment level was good.

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty ref

Date: _____

1/15/10

CERTIFIED REPORT IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |


COMMENTS/ OTHER INFORMATION

None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Pasture Sediment Pond

GENERAL INFORMATION

Report Date January 12, 2010
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name Pasture Sediment Pond
Impoundment Number 009
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date December 17, 2009
Inspected by Rusty Netz
Reason for Inspection Fourth Quarter Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 3.2 Acre-feet
Pond bottom elevation = 6484.5
100% Sediment Storage Volume = 0.42 acre-feet at Elevation 6486.2
60% sediment Storage Volume = 0.25 acre feet at Elevation = 6485.5
Existing Sediment Elevation = 6485.1 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6486.6
Emergency Spillway Elevation = 6490.6

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on outslopes of embankments, etc.

Pond had some water in it. No samples were taken Pond did not require decanting.
Sediment level was good
Embankment conditions were good. Vegetation on outslopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Pasture Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure were observed.

A small amount of water was impounded

Sediment level was good.

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty Nety

Date: _____

1/15/10

CERTIFIED REPORT IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |


COMMENTS/ OTHER INFORMATION

None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Coarse Refuse Toe Sediment Pond

GENERAL INFORMATION

Report Date January 12, 2010
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name New Coarse Refuse Toe Sediment Pond
Impoundment Number 012
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date December 17, 2009
Inspected by Rusty Netz
Reason for Inspection Fourth Quarter Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 1.6 Acre-feet
Pond bottom elevation = 6176.0
100% Sediment Storage Volume = 0.07 acre-feet at Elevation 6177.8
60% sediment Storage Volume = 0.03 acre feet at Elevation = 6177.0
Existing Sediment Elevation = 6176.6 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6178.2
Emergency Spillway Elevation = 6183.63

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond had some water in it. No samples were taken Pond did not require decanting
Sediment level was good
Embankment conditions were good. Vegetation on out slopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Coarse Refuse Toe Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure have been observed

Some water was impounded

Sediment level was good.

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty Nut

Date: _____

1/15/10

CERTIFIED REPORT

IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |


COMMENTS/ OTHER INFORMATION

None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

GENERAL INFORMATION

Coal Pile Sediment Pond

Report Date January 12, 2010
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name Coal Pile Sediment Pond
Impoundment Number 014
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date December 17, 2009
Inspected by Rusty Netz
Reason for Inspection Fourth Quarter Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 1.5 Acre-feet
Pond bottom elevation = 6473.0
100% Sediment Storage Volume = 0.5 acre-feet at Elevation 6476.0
60% sediment Storage Volume = 0.3 acre feet at Elevation = 6474.7
Existing Sediment Elevation = 6474 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6476.0
Secondary Dewatering Orifice = 6477.2
Primary Spillway Elevation = 6477.9
Emergency Spillway Elevation = 6479.0

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on outslopes of embankments, etc.

Pond had some water in it. No samples were taken Pond did not require decanting.
Sediment level was good.
Embankment conditions were good. Vegetation on outslopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Coal Pile Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure have been observed

A small amount of water was impounded

Sediment level was good.

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Date: _____

CERTIFIED REPORT

IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |


COMMENTS/ OTHER INFORMATION

None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Borrow Area Sediment Pond

GENERAL INFORMATION

Report Date January 12, 2010
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name Borrow Area Sediment Pond
Impoundment Number 016
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date December 17, 2009
Inspected by Rusty Netz
Reason for Inspection Fourth Quarter Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 8.3 Acre-feet
Pond bottom elevation = 6510.0
100% Sediment Storage Volume = 2.3 acre-feet at Elevation 6514.3
60% sediment Storage Volume = 1.4 acre feet at Elevation = 6513.3
Existing Sediment Elevation = 6511 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6514.3
Emergency Spillway Elevation = 6517.03

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on outslopes of embankments, etc.

Pond had no water in it. No samples were taken
Sediment level was good. Pond did not require decanting.
Embankment conditions were good. Vegetation on outslopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Borrow Area Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure have been observed

No water was impounded

Sediment level was good.

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty Rety

Date: _____

1/15/10

CERTIFIED REPORT

IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |


COMMENTS/ OTHER INFORMATION

None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

GENERAL INFORMATION

Coarse Refuse Pile

Report Date January 12, 2010
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

EXCESS SPOIL PILE OR REFUSE PILE IDENTIFICATION

Pile Name Coarse Refuse Pile
Pile Number N/A
MSHA ID Number 1211-UT-09-02093-01

Inspection Date December 17, 2009
Inspected by Rusty Netz
Reason for Inspection Fourth Quarter Inspection 2009

Attachment to Report? (such as refuse sample analysis or photos) **NO**

Field Evaluation

1. Foundation preparation, including the removal of all organic material and topsoil.

N/A

2. Placement of underdrains and protective filter systems.

N/A

3. Installation of final surface drainage systems

N/A

4. Placement and compaction of fill materials

N/A - Activities occurring at this time are associated with removal of refuse material

5. Final grading and revegetation of fill.

N/A

6. Appearances of instability, structural weakness, and other hazardous conditions

No aspects of the Fill structure were observed that could affect its stability or functionality

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

Coarse Refuse Pile

7. Other comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period

Refuse material is actively being excavated and removed from various locations across the top of the pile

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty Nitz

Date: _____


1/15/10

CERTIFICATION STATEMENT

I hereby certify that: I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with the approved design and meets or exceeds the minimum design requirements under all applicable federal, state, and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH

Affix Signature, Stamp and Date



INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

GENERAL INFORMATION

Excess Spoil Disposal Area #1

Report Date January 12, 2010
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

EXCESS SPOIL PILE OR REFUSE PILE IDENTIFICATION

Pile Name Excess Spoil Disposal Area #1
Pile Number N/A
MSHA ID Number 1211-UT-09-02093-04

Inspection Date December 17, 2009
Inspected by Rusty Netz
Reason for Inspection Fourth Quarter Inspection 2009

Attachment to Report? (such as refuse sample analysis or photos) **NO**

Field Evaluation

1. Foundation preparation, including the removal of all organic material and topsoil.

N/A

2. Placement of underdrains and protective filter systems.

N/A

3. Installation of final surface drainage systems

N/A

4. Placement and compaction of fill materials

No new material was placed during the quarter.

5. Final grading and revegetation of fill.

N/A

6. Appearances of instability, structural weakness, and other hazardous conditions

No aspects of the Fill structure were observed that could affect its stability or functionality

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

Excess Spoil Disposal Area #1

7. Other comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period

Construction of the fill has been proceeding in shallow lifts in general conformance with the approved plan.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty Neth

Date: _____


1/15/10

CERTIFICATION STATEMENT

I hereby certify that: I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with the approved design and meets or exceeds the minimum design requirements under all applicable federal, state, and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH

Affix Signature, Stamp and Date



INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

GENERAL INFORMATION

Excess Spoil Disposal Area #2

Report Date January 12, 2010
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

EXCESS SPOIL PILE OR REFUSE PILE IDENTIFICATION

Pile Name Excess Spoil Disposal Area #2
Pile Number N/A
MSHA ID Number 1211-UT-09-02093-05

Inspection Date December 17, 2009
Inspected by Rusty Netz
Reason for Inspection Fourth Quarter Inspection 2009

Attachment to Report? (such as refuse sample analysis or photos) **NO**

Field Evaluation

1. Foundation preparation, including the removal of all organic material and topsoil.

Existing disturbed site. No additional topsoil removal is required by the approved plan

2. Placement of underdrains and protective filter systems.

No under-drains or filters area required by the approved plan

3. Installation of final surface drainage systems

N/A

4. Placement and compaction of fill materials

Approximately 16,275 tons of material were placed in this disposal area during the quarter.

5. Final grading and revegetation of fill.

N/A

6. Appearances of instability, structural weakness, and other hazardous conditions

No aspects of the Fill structure were observed that could affect its stability or functionality

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

Excess Spoil Disposal Area #2

7. Other comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period

Construction of the fill has been proceeding in shallow lifts in general conformance with the approved plan.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty Notz


Date: _____

1/15/10


CERTIFICATION STATEMENT

I hereby certify that: I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with the approved design and meets or exceeds the minimum design requirements under all applicable federal, state, and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH




Affix Signature, Stamp and Date



APPENDIX A CERTIFIED REPORTS

ANNUAL INSPECTION

IMPOUNDMENTS, REFUSE PILE AND DISPOSAL AREAS



Sunnyside Cogeneration Associates

P.O. Box 10, East Carbon, Utah 84520 • (435) 888-4476 • Fax (435) 888-2538

January 15, 2010

Daron Haddock
Division of Oil, Gas & Mining
1594 W. North Temple, Suite 1210
Salt Lake City, Utah 84116

RE: Annual 2009 Inspection Report
Sunnyside Refuse and Slurry C/007/035

Dear Mr. Haddock:

Please find enclosed a copy of the Annual 2009 Inspection Report for the Sunnyside refuse pile, impoundments, and excess spoil areas.

Should you have any questions, please contact Rusty Netz or myself at (435)888-4476.

Thank You,

Richard Carter
Agent For
Sunnyside Cogeneration Associates

c.c. Steve Gross
William Rossiter
Paul Shepard
Maggie Estrada
Rusty Netz
Plant File

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

GENERAL INFORMATION

Railcut Sediment Pond

Report Date January 12, 2010
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name RailCut Sediment Pond
Impoundment Number 007
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date December 17, 2009
Inspected by Rusty Netz
Reason for Inspection Annual Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 4.8 Acre-feet
Pond bottom elevation = 6206.0
100% Sediment Storage Volume = 0.34 acre-feet at Elevation 6209
60% sediment Storage Volume = 0.2 acre feet at Elevation = 6207.7
Existing Sediment Elevation = 6207.2 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6209.07
Emergency Spillway Elevation = 6212.34

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond had some water in it. No samples were taken Pond did not require decanting
Sediment levels were good
Embankment conditions were good. Vegetation on out slopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Rail Cut Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure have been observed

Some water was impounded

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty net

Date: _____

1/15/10

CERTIFIED REPORT

IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |


COMMENTS/ OTHER INFORMATION

None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Old Coarse Refuse Road Sediment Pond

GENERAL INFORMATION

Report Date January 12, 2010
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name Old Coarse Refuse Road Sediment Pond
Impoundment Number 008
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date December 17, 2009
Inspected by Rusty Netz
Reason for Inspection Annual Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 0.9 Acre-feet
Pond bottom elevation = 6394.0
100% Sediment Storage Volume = 0.08 acre-feet at Elevation 6395.1
60% sediment Storage Volume = 0.05 acre feet at Elevation = 6394.75
Existing Sediment Elevation = 6394.4 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6395.75
Emergency Spillway Elevation = 6399.4

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond had some water in it. No samples were taken Pond did not require decanting.
Sediment level was good.
Embankment conditions were good. Vegetation on out slopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Old Coarse Refuse Road Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure have been observed

Some water was impounded

Sediment level was good.

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty Rely

Date: _____

1/15/10

CERTIFIED REPORT

IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |


COMMENTS/ OTHER INFORMATION

None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Pasture Sediment Pond

GENERAL INFORMATION

Report Date January 12, 2010
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name Pasture Sediment Pond
Impoundment Number 009
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date December 17, 2009
Inspected by Rusty Netz
Reason for Inspection Annual Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 3.2 Acre-feet
Pond bottom elevation = 6484.5
100% Sediment Storage Volume = 0.42 acre-feet at Elevation 6486.2
60% sediment Storage Volume = 0.25 acre feet at Elevation = 6485.5
Existing Sediment Elevation = 6485.1 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6486.6
Emergency Spillway Elevation = 6490.6

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond had some water in it. No samples were taken Pond did not require decanting.
Sediment level was good
Embankment conditions were good. Vegetation on out slopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Pasture Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure were observed.

A small amount of water was impounded

Sediment level was good.

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: Rusty [Signature] Date: 1/15/10

CERTIFIED REPORT IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |


COMMENTS/ OTHER INFORMATION

None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Coarse Refuse Toe Sediment Pond

GENERAL INFORMATION

Report Date January 12, 2010
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name New Coarse Refuse Toe Sediment Pond
Impoundment Number 012
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date December 17, 2009
Inspected by Rusty Netz
Reason for Inspection Annual Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 1.6 Acre-feet
Pond bottom elevation = 6176.0
100% Sediment Storage Volume = 0.07 acre-feet at Elevation 6177.8
60% sediment Storage Volume = 0.03 acre feet at Elevation = 6177.0
Existing Sediment Elevation = 6176.6 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6178.2
Emergency Spillway Elevation = 6183.63

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond had some water in it. No samples were taken Pond did not require decanting
Sediment level was good
Embankment conditions were good. Vegetation on out slopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Coarse Refuse Toe Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure have been observed

Some water was impounded

Sediment level was good.

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty Nely

Date: _____

1/15/10

CERTIFIED REPORT

IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |


COMMENTS/ OTHER INFORMATION

None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

GENERAL INFORMATION

Coal Pile Sediment Pond

Report Date January 12, 2010
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name Coal Pile Sediment Pond
Impoundment Number 014
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date December 17, 2009
Inspected by Rusty Netz
Reason for Inspection Annual Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 1.5 Acre-feet
Pond bottom elevation = 6473.0
100% Sediment Storage Volume = 0.5 acre-feet at Elevation 6476.0
60% sediment Storage Volume = 0.3 acre feet at Elevation = 6474.7
Existing Sediment Elevation = 6474 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6476.0
Secondary Dewatering Orifice = 6477.2
Primary Spillway Elevation = 6477.9
Emergency Spillway Elevation = 6479.0

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond had some water in it. No samples were taken Pond did not require decanting.
Sediment level was good.
Embankment conditions were good. Vegetation on out slopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Coal Pile Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure have been observed

A small amount of water was impounded

Sediment level was good.

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty Rely

Date: _____

1/15/10

CERTIFIED REPORT IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |


COMMENTS/ OTHER INFORMATION

None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Borrow Area Sediment Pond

GENERAL INFORMATION

Report Date January 12, 2010
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

IMPOUNDMENT IDENTIFICATION

Impoundment Name Borrow Area Sediment Pond
Impoundment Number 016
UPDES Permit Number UT024759
MSHA ID Number N/A

IMPOUNDMENT INSPECTION

Inspection Date December 17, 2009
Inspected by Rusty Netz
Reason for Inspection Annual Inspection 2009

1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.

None

a. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and estimated average elevation of existing sediment.

Total Pond Volume = 8.3 Acre-feet
Pond bottom elevation = 6510.0
100% Sediment Storage Volume = 2.3 acre-feet at Elevation 6514.3
60% sediment Storage Volume = 1.4 acre feet at Elevation = 6513.3
Existing Sediment Elevation = 6511 +/-

b. Principle and emergency spillway elevations.

Primary Dewatering Pipe = 6514.3
Emergency Spillway Elevation = 6517.03

2. Field Information

Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/ instrumentation information, inlet/ outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/ repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond had no water in it. No samples were taken
Sediment level was good. Pond did not require decanting.
Embankment conditions were good. Vegetation on out slopes was adequate.
Inlet / Outlet conditions were good. No structural or hazardous conditions were observed.

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Borrow Area Sediment Pond

3. Field Evaluation.

Describe any changes in the geometry of the impounding structure, average and maximum depths and elevation of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period

No recent changes in the geometry of the structure have been observed

No water was impounded

Sediment level was good.

No other aspects of the impounding structure were observed that could affect its stability or functionality.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty Nety

Date: _____

1/15/10

CERTIFIED REPORT IMPOUNDMENT EVALUATION

If you answer NO to these questions, please explain under comments

- | | |
|--|------------|
| 1. Is impoundment designed and constructed in accordance with the approved plan? | <u>YES</u> |
| 2. Is impoundment free of instability, structural weakness, or any other hazardous conditions? | <u>YES</u> |
| 3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection? | <u>YES</u> |


COMMENTS/ OTHER INFORMATION

None

CERTIFICATION STATEMENT:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved designs and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH



Affix Signature, Stamp and Date

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

GENERAL INFORMATION

Coarse Refuse Pile

Report Date January 12, 2010
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

EXCESS SPOIL PILE OR REFUSE PILE IDENTIFICATION

Pile Name Coarse Refuse Pile
Pile Number N/A
MSHA ID Number 1211-UT-09-02093-01

Inspection Date December 17, 2009
Inspected by Rusty Netz
Reason for Inspection Annual Inspection 2009

Attachment to Report? (such as refuse sample analysis or photos) **NO**

Field Evaluation

1. Foundation preparation, including the removal of all organic material and topsoil.

N/A

2. Placement of underdrains and protective filter systems.

N/A

3. Installation of final surface drainage systems

N/A

4. Placement and compaction of fill materials

N/A - Activities occurring at this time are associated with removal of refuse material

5. Final grading and revegetation of fill.

N/A

6. Appearances of instability, structural weakness, and other hazardous conditions

No aspects of the Fill structure were observed that could affect its stability or functionality

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

Coarse Refuse Pile

7. Other comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period

Refuse material is actively being excavated and removed from various locations across the top of the pile

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty ref

Date: _____


1/15/10

CERTIFICATION STATEMENT

I hereby certify that: I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with the approved design and meets or exceeds the minimum design requirements under all applicable federal, state, and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH

Affix Signature, Stamp and Date



INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

GENERAL INFORMATION

Excess Spoil Disposal Area #1

Report Date January 12, 2010
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

EXCESS SPOIL PILE OR REFUSE PILE IDENTIFICATION

Pile Name Excess Spoil Disposal Area #1
Pile Number N/A
MSHA ID Number 1211-UT-09-02093-04

Inspection Date December 17, 2009
Inspected by Rusty Netz
Reason for Inspection Annual Inspection 2009

Attachment to Report? (such as refuse sample analysis or photos) **NO**

Field Evaluation

1. Foundation preparation, including the removal of all organic material and topsoil.

N/A

2. Placement of underdrains and protective filter systems.

N/A

3. Installation of final surface drainage systems

N/A

4. Placement and compaction of fill materials

No new material was placed during the year.

5. Final grading and revegetation of fill.

N/A

6. Appearances of instability, structural weakness, and other hazardous conditions

No aspects of the Fill structure were observed that could affect its stability or functionality

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

Excess Spoil Disposal Area #1

7. Other comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period

Construction of the fill has been proceeding in shallow lifts in general conformance with the approved plan.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty net

Date: _____


1/15/10

CERTIFICATION STATEMENT

I hereby certify that: I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with the approved design and meets or exceeds the minimum design requirements under all applicable federal, state, and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: S. Scott Carlson, PE, Twin Peaks, P.C.
P.E. Number & State: 187727 UTAH

Affix Signature, Stamp and Date



INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

GENERAL INFORMATION

Excess Spoil Disposal Area #2

Report Date January 12, 2010
Permit Number C/007/035
Mine Name Sunnyside Refuse and Slurry
Company Name Sunnyside Cogeneration Associates

EXCESS SPOIL PILE OR REFUSE PILE IDENTIFICATION

Pile Name Excess Spoil Disposal Area #2
Pile Number N/A
MSHA ID Number 1211-UT-09-02093-05

Inspection Date December 17, 2009
Inspected by Rusty Netz
Reason for Inspection Annual Inspection 2009

Attachment to Report? (such as refuse sample analysis or photos) **NO**

Field Evaluation

1. Foundation preparation, including the removal of all organic material and topsoil.

Existing disturbed site. No additional topsoil removal is required by the approved plan

2. Placement of underdrains and protective filter systems.

No under-drains or filters area required by the approved plan

3. Installation of final surface drainage systems

N/A

4. Placement and compaction of fill materials

Approximately **65,564 tons** (11,519 Q1; 20,130 Q2; 17,640 Q3; 16,275 Q4) of material were placed in this disposal area during the year.

5. Final grading and revegetation of fill.

N/A

6. Appearances of instability, structural weakness, and other hazardous conditions

No aspects of the Fill structure were observed that could affect its stability or functionality

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE

Excess Spoil Disposal Area #2

7. Other comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period

Construction of the fill has been proceeding in shallow lifts in general conformance with the approved plan.

QUALIFICATION STATEMENT:

I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and that inspections are made by myself and include any appearances of instability, structural weakness or other hazardous condition of the structure affecting stability.

Signature: _____

Rusty ref

Date: _____

1/15/10


CERTIFICATION STATEMENT


I hereby certify that: I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with the approved design and meets or exceeds the minimum design requirements under all applicable federal, state, and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: S. Scott Carlson, PE, Twin Peaks, P.C.

P.E. Number & State: 187727 UTAH

Affix Signature, Stamp and Date





APPENDIX B-1 CLIMATOLOGICAL DATA

SUNNYSIDE WEATHER STATION 2009 CLIMATOLOGICAL REPORT


day	January			February			March			April			May			June		
	max temp	min temp	precip	max temp	min temp	precip	max temp	min temp	precip	max temp	min temp	precip	max temp	min temp	precip	max temp	min temp	precip
1	37	23		47	28		53	34		47	28	t	71	49		75	53	0.07
2	37	26		48	26		58	35		51	29	0.1	61	46	0.55	72	52	
3	39	25		49	31		60	47		51	34		61	42		76	49	0.05
4	31	16		50	32		65	47		40	30		63	45		77	52	
5	29	14		50	33		61	33		46	26	0.5	62	45		77	58	
6	34	18		48	34		46	34		52	29					73	44	
7	46	23		46	35	0.12	44	30		58	33		74.2			70	44	
8	46	30		50	35	0.1	46	26		59	40		72	44		71	50	0.04
9	43	27		41	29		49	34		52	37		66	41		69	51	0.07
10	41	21		39	22		44	21		58	41		68	52		66	45	0.03
11	42	27		39	22		48	26		57	36	0.3	76	46		66	47	
12	45	30		39	28		54	32		60	37	0.08	77	45		71	44	
13	45	27		38	21		55	35		60	37		75	50		72	56	0.03
14	42	29		37	29	0.06	55	31		61	44		71	44		74	49	
15	45	29		39	21		56	34		56	36	0.37	72	47		72	48	
16	45	30		43	27		60	36		41	28		76	50		73	55	0.1
17	47	29		44	30	0.18	63	39		46	36		79	52		70	50	0.06
18	47	33		41	23		64	46		57	40		85	55		68	48	
19	53	35		43	22		65	41		64	39		86	60		74	44	
20	54	35		45	27		68	43		70	41		78	50		75	53	0.63
21	51	33		49	29		68	42		71	45		79	56		68	47	0.08
22	48	34		50	32		64	43		73	46		75	52		78	47	
23	48	36		48	38	0.10	48	33		74	46		62	50		85	56	
24	47	36		52	37	t	48	29		73	59		65	50	0.75	88	60	
25	47	36	0.4	55	36		47	32		67	44	0.67	64	46	1.44	88	62	
26	43	30		55	34		48	29	t	48	32	0.06	67	46	0.1	86	55	0.44
27	33	14	0.3	55	32		47	23		52	29		70	46		50	51	
28	35	21		53	34		55	28		66	42		74	50	0.37	85	57	
29	40	21					57	37		67	42		75	49		87	57	
30	42	26					40	25		72	46		76	50		90	60	
31	44	28					48	27					76	51	0.1			
Total	1326	842	0.7	1293	827	0.56	1684	1052	0.00	1749	1132	2.08	2156.2	1409	3.31	2246	1544	1.6
AVG	42.77	27.16		46.18	29.54		54.32	33.94		58.30	37.73		71.87	48.59		74.87	51.47	
AVG DAILY	34.97			37.86			44.13			48.02			60.23			63.17		

temperature in °F
precipitation in inches


SUNNYSIDE WEATHER STATION 2009 CLIMATOLOGICAL REPORT

day	July			August			September			October			November			December		
	max temp	min temp	precip	max temp	min temp	precip	max temp	min temp	precip	max temp	min temp	precip	max temp	min temp	precip	max temp	min temp	precip
1	90	65		88	59		86	58		52	30		56	35		51	32	
2	87	65	t	92	61		88	62		59	35		61	40		51	32	
3	82	56		91	65		88	59		59	40		61	41		40	28	
4	82	60	0.28	92	61		87	59		62	48		62	40		35	15	
5	85	57		91	64		88	59		61	37		63	41		35	19	
6	87	58		88	61	t	79	55		55	32		64	42		36	22	
7	89	57		85	54		82	55		62	37		64	41		29	19	0.6
8	89	56		80	50		83	57		61	39		63	38		30	24	0.3
9	89	59		76	48		86	58		60	36		58	38		25	11	
10	89	58		83	54		86	62		62	42		58	38		26	13	
11	89	65		87	59		86	58		62			59	42		27	15	
12	88	60		89	61		86	57		62		t	58	49		26	20	
13	91	61		86	60		83	57		63	46		56	36		34	25	1.8
14	91	56		81	55	0.35	75	52	0.9	61	48	0.53	46	30	t	36	25	
15	90	59		80	56		75	48	0.3	65	45	0.12	42	24		37	23	
16	91	64		77	48		73	49		66	42		43	26		38	26	
17	93	66		79	52		74	51		68	45		47	29		42	26	
18	95	69		80	55		75	52		70	46		48	29		41	28	
19	92	65		85	55		76	52		71	49		52	32		41	23	
20	91	62		88	62		75	55		71	49		52	32		37	24	
21	92	62		91	62		76	46		58	41		48	33		36	24	
22	93	64		92	63		66	40		61	39		44	27	t	36	26	0.3
23	95	63		92	60		69	47		62	39		44	24		41	29	
24	95	69		79	55	0.25	74	48		61	41		41	25		40	16	
25	88	65		79	56		79	49		57	34		50	30		32	18	
26	87	66		88	54		81	53		52	31		53	35		31	18	
27	89	59	0.12	88	59		83	54		50	36		53	30		33	20	
28	89	62		89	61		84	57		42	29		48	35		33	19	
29	90	60		90	62		81	53		38	28		53	37		32	22	
30	88	58		91	64		79	46		50	28		53	33		29	20	0.12
31	85	61		89	58					53	32					33	19	
Total	2771	1907	0.4	2666	1794	0.6	2403	1608	1.20	1836	1124	0.65	1600	1032	0	1093	681	3.12
AVG	89.39	61.52		86.00	57.87		80.10	53.60		59.23	38.76		53.33	34.40		35.26	21.97	
AVG DAILY	75.45			71.94			66.85			48.99			43.87			28.61		

AVERAGE HIGH TEMPERATURE 62.63
 AVERAGE LOW TEMPERATURE 41.38
 TOTAL PRECIPITATION FOR 2009 14.22
 AVERAGE MONTHLY PRECIPITATION 1.19




APPENDIX B-2 WATER MONITORING



APPENDIX B-2 WATER MONITORING

FIRST QUARTER



Sunnyside Cogeneration Associates

P.O. Box 10, East Carbon, Utah 84520 • (435) 888-4476 • Fax (435) 888-2538

April 21, 2009

Darron Haddock
Division of Oil, Gas & Mining
1594 W. North Temple, Suite 1210
Salt Lake City, Utah 84116

Subject: Quarterly Sampling Report
Monitoring Period: January, February, March 2009
DOGM Operational Water Monitoring

Dear Darron:

This letter is to confirm that the quarterly baseline water sampling data and the UPDES DMR data, have been submitted to the DOGM EDI web site. The data is correct and ready to be processed.

Should you have any questions, please contact Rusty Netz or myself at (435) 888-4476.

Thank You,

Michael J. Blakey
Agent For
Sunnyside Cogeneration Associates

c.c. Steve Gross
William Rossiter
Maggie Estrada
Paul Shepard
Rusty Netz
Plant File

Sunnyside Cogeneration Facility
Sunnyside, Utah

Field Parameter Data

DOGM Permit Boundary Water Quality Monitoring Plan
Monitoring Period: First Quarter 2009
Samples taken March 17, 2009

Monitoring Location	Location I.D.	Temp. (C)	pH (su)	SC (umhos)	Dissolved Oxygen (mg/l)	Flow Rate (gpm)	Flow method
Iceland Creek	ICE-1	NA	NA	NA	NA	NA	NA
Columbia Dugway Spring	F-2	4.1	8.56	1509	11	20	2
Coarse Refuse Seep Source	CRS	NA	NA	NA	NA	NA	NA
Coarse Refuse Seep Boundary	CRB	5.8	8.24	6730	6.7	45	2
Dragerton Well	Well-1	11.8	7.84	1200	8.9	260	4
Borehole B-6	B-6	NW	NW	NW	NW	NW	NW

Notes:

na - no flow

NW - no water present

NW/F - no water present frozen


nd - data is not available due to lack of discharge

1 - Flow rates were measured using a weir.

2 - Flow rates were measured using a calibrated container and stopwatch method.

3 - Flow rates were measured using the floating debris method.

4 - Flow rates were measured using a meter



Analysis Report

April 06, 2009

APR - 9 2009

Page 1 of 2

SUNNYSIDE COGENERATION FAC
PO BOX 10
EAST CARBON UT 84520

Client Sample ID: CRB
Date Sampled: Mar 17, 2009
Date Received: Mar 18, 2009
Product Description: WATER

Sample ID By: Sunnyside Cogeneration Assoc.
Sample Taken At: CRB
Sample Taken By: Richard Safley
Time Sampled: 0900
Time Received: 1010
Mine: 27
Site: 9
Field - pH: 8.2
Field - Dis. Oxygen: 6.7 MG/L
Field - Flow: 45 GPM
Field - Conductivity: 6730 UMHOS/CM
Field - Temperature: 5.8 DEG. C

Comments: Dissolved Metals Filtered at Lab
pH Expired When Received

SGS Minerals Sample ID: 782-0901004-001

Tests	Result	Unit	Method	REPORTING	ANALYZED		
				LIMIT	DATE	TIME	ANALYST
Hardness, mg equivalent CaCO ₃ /L	3318	mg/L	SM2340-B	1.000	03/30/2009	15:41	SJ
Oil and Grease, (HEM)	<5	mg/L	EPA 1664	5.000	03/20/2009	09:30	CM
Sulfate, SO ₄	4212	mg/L	EPA 300.0	1.000	03/26/2009	23:11	CM
Anions	99.60	meq/L	SM1030	0.000	03/30/2009	15:40	SJ
Cations	109.60	meq/L	SM1030	0.000	03/30/2009	15:40	SJ
Balance	4.80	%	SM1030	-10.000	03/30/2009	15:40	SJ
pH	8.04	s. u.	SM4500-H	0.010	03/18/2009	11:15	CM
pH Temperature	14.70	°C	SM4500-H	0.010	03/18/2009	11:15	CM
Settleable Solids	<0.1	mL/L	SM2540-F a	0.100	03/18/2009	14:30	CM
Total Dissolved Solids	7022	mg/L	SM2540-C	30.000	03/19/2009	11:45	GK
Total Suspended Solids	<5	mg/L	SM2540-D	5.000	03/19/2009	11:45	GK
Chloride, Cl	160	mg/L	EPA 300.0	1.000	03/26/2009	23:11	CM
Alkalinity, mg CaCO ₃ /L (pH 4.5)	368	mg/L	SM2320-B	5.000	03/18/2009	14:20	AL
Carbonate Alkalinity as CaCO ₃	<5	mg/L	SM2320-B	5.000	03/18/2009	14:20	AL
Bicarbonate Alkalinity as CaCO ₃	368	mg/L	SM2320-B	5.000	03/18/2009	14:20	AL

Respectfully submitted,
SGS NORTH AMERICA INC.

Huntington Laboratory



Analysis Report

April 06, 2009

SUNNYSIDE COGENERATION FAC
PO BOX 10
EAST CARBON UT 84520

Page 2 of 2

APR - 9 2009

Client Sample ID: CRB
Date Sampled: Mar 17, 2009
Date Received: Mar 18, 2009
Product Description: WATER


Sample ID By: Sunnyside Cogeneration Assoc.
Sample Taken At: CRB
Sample Taken By: Richard Safley
Time Sampled: 0900
Time Received: 1010
Mine: 27
Site: 9
Field - pH: 8.2
Field - Dis. Oxygen: 6.7 MG/L
Field - Flow: 45 GPM
Field - Conductivity: 6730 UMHOS/CM
Field - Temperature: 5.8 DEG. C

Comments: Dissolved Metals Filtered at Lab
pH Expired When Received

SGS Minerals Sample ID: 782-0901004-001


<u>Tests</u>	<u>Result</u>	<u>Unit</u>	<u>Method</u>	<u>REPORTING</u>	<u>ANALYZED</u>		
				<u>LIMIT</u>	<u>DATE</u>	<u>TIME</u>	<u>ANALYST</u>
METALS BY ICP							
Calcium, Ca - Dissolved	501.05	mg/L	EPA 200.7	0.030	03/26/2009	17:22	CM
Iron, Fe - Total	<0.05	mg/L	EPA 200.7	0.050	03/24/2009	18:44	CM
Iron, Fe - Dissolved	<0.03	mg/L	EPA 200.7	0.030	03/19/2009	17:39	CM
Magnesium, Mg - Dissolved	501.91	mg/L	EPA 200.7	0.010	03/26/2009	17:22	CM
Manganese, Mn - Total	0.014	mg/L	EPA 200.7	0.002	03/24/2009	18:44	CM
Manganese, Mn - Dissolved	0.013	mg/L	EPA 200.7	0.002	03/19/2009	17:39	CM
Potassium, K - Dissolved	45.55	mg/L	EPA 200.7	0.140	03/19/2009	17:39	CM
Sodium, Na - Dissolved	969.06	mg/L	EPA 200.7	0.090	03/26/2009	17:22	CM

Respectfully submitted,
SGS NORTH AMERICA INC.


Huntington Laboratory

SGS North America Inc. | Minerals Services Division
P.O. Box 1020, Huntington, UT 84528 t (435) 653-2311 f (435) 653-2436 www.us.sgs.com/minerals

Member of the SGS Group



Analysis Report

April 06, 2009

SUNNYSIDE COGENERATION FAC
PO BOX 10
EAST CARBON UT 84520

APR - 9 2009

Page 1 of 2

Client Sample ID: F2
Date Sampled: Mar 17, 2009
Date Received: Mar 18, 2009
Product Description: WATER

Sample ID By: Sunnyside Cogeneration Assoc.
Sample Taken At: F2
Sample Taken By: Richard Safley
Time Sampled: 0945
Time Received: 1010
Mine: 27
Site: 11
Field - pH: 8.56
Field - Dis. Oxygen: 11 MG/L
Field - Flow: 15-20 GPM
Field - Conductivity: 1509 UMHOS/CM
Field - Temperature: 4.1 DEG. C

Comments: Dissolved Metals Filtered at Lab
pH Expired When Received

SGS Minerals Sample ID: 782-0901004-002

Tests	Result	Unit	Method	REPORTING	ANALYZED		
				LIMIT	DATE	TIME	ANALYST
Hardness, mg equivalent CaCO ₃ /L	523	mg/L	SM2340-B	1.000	03/30/2009	15:41	SJ
Oil and Grease, (HEM)	<5	mg/L	EPA 1664	5.000	03/20/2009	09:30	CM
Sulfate, SO ₄	406	mg/L	EPA 300.0	1.000	03/20/2009	03:06	AL
Anions	18.20	meq/L	SM1030	0.000	03/30/2009	15:40	SJ
Cations	18.70	meq/L	SM1030	0.000	03/30/2009	15:40	SJ
Balance	1.40	%	SM1030	-10.000	03/30/2009	15:40	SJ
pH	8.41	s. u.	SM4500-H	0.010	03/18/2009	11:17	CM
pH Temperature	14.30	°C	SM4500-H	0.010	03/18/2009	11:17	CM
Settleable Solids	<0.1	mL/L	SM2540-F a	0.100	03/18/2009	14:30	CM
Total Dissolved Solids	1070	mg/L	SM2540-C	30.000	03/19/2009	11:45	GK
Total Suspended Solids	5	mg/L	SM2540-D	5.000	03/19/2009	11:45	GK
Chloride, Cl	27	mg/L	EPA 300.0	1.000	03/19/2009	23:25	AL
Alkalinity, mg CaCO ₃ /L (pH 4.5)	449	mg/L	SM2320-B	5.000	03/18/2009	14:20	AL
Carbonate Alkalinity as CaCO ₃	14	mg/L	SM2320-B	5.000	03/18/2009	14:20	AL
Bicarbonate Alkalinity as CaCO ₃	435	mg/L	SM2320-B	5.000	03/18/2009	14:20	AL

Respectfully submitted,
SGS NORTH AMERICA INC.

Allen Ludington
Huntington Laboratory



Analysis Report

April 06, 2009

SUNNYSIDE COGENERATION FAC
PO BOX 10
EAST CARBON UT 84520

APR - 9 2009

Page 2 of 2

Client Sample ID: F2
Date Sampled: Mar 17, 2009
Date Received: Mar 18, 2009
Product Description: WATER

Sample ID By: Sunnyside Cogeneration Assoc.
Sample Taken At: F2
Sample Taken By: Richard Safley
Time Sampled: 0945
Time Received: 1010
Mine: 27
Site: 11
Field - pH: 8.56
Field - Dis. Oxygen: 11 MG/L
Field - Flow: 15-20 GPM
Field - Conductivity: 1509 UMHOS/CM
Field - Temperature: 4.1 DEG. C


Comments: Dissolved Metals Filtered at Lab
pH Expired When Received

SGS Minerals Sample ID: 782-0901004-002

<u>Tests</u>	<u>Result</u>	<u>Unit</u>	<u>Method</u>	REPORTING	ANALYZED		
				<u>LIMIT</u>	<u>DATE</u>	<u>TIME</u>	<u>ANALYST</u>
METALS BY ICP							
Calcium, Ca - Dissolved	76.85	mg/L	EPA 200.7	0.030	03/19/2009	17:39	CM
Iron, Fe - Total	0.29	mg/L	EPA 200.7	0.050	03/24/2009	18:44	CM
Iron, Fe - Dissolved	<0.03	mg/L	EPA 200.7	0.030	03/19/2009	17:39	CM
Magnesium, Mg - Dissolved	90.07	mg/L	EPA 200.7	0.010	03/19/2009	17:39	CM
Manganese, Mn - Total	0.014	mg/L	EPA 200.7	0.002	03/24/2009	18:44	CM
Manganese, Mn - Dissolved	0.007	mg/L	EPA 200.7	0.002	03/19/2009	17:39	CM
Potassium, K - Dissolved	2.94	mg/L	EPA 200.7	0.140	03/19/2009	17:39	CM
Sodium, Na - Dissolved	170.27	mg/L	EPA 200.7	0.090	03/19/2009	17:39	CM

Respectfully submitted,
SGS NORTH AMERICA INC.


Huntington Laboratory



Analysis Report

April 06, 2009

SUNNYSIDE COGENERATION FAC
PO BOX 10
EAST CARBON UT 84520

APR - 9 2009

Page 1 of 2

Client Sample ID: Well 1
Date Sampled: Mar 17, 2009
Date Received: Mar 18, 2009
Product Description: WATER

Sample ID By: Sunnyside Cogeneration Assoc.
Sample Taken At: Well 1
Sample Taken By: Richard Safley
Time Sampled: 1009
Time Received: 1010
Mine: 27
Site: 8
Field - pH: 7.84
Field - Dis. Oxygen: 8.9 MG/L
Field - Flow: 260 GPM
Field - Conductivity: 1200 UMHOS/CM
Field - Temperature: 11.8 DEG. C

Comments: Dissolved Metals Filtered at Lab
pH Expired When Received

SGS Minerals Sample ID: 782-0901004-003

Tests	Result	Unit	Method	REPORTING	ANALYZED		
				LIMIT	DATE	TIME	ANALYST
Hardness, mg equivalent CaCO ₃ /L	443	mg/L	SM2340-B	1.000	03/30/2009	15:41	SJ
Oil and Grease, (HEM)	<5	mg/L	EPA 1664	5.000	03/20/2009	09:30	CM
Sulfate, SO ₄	228	mg/L	EPA 300.0	1.000	03/20/2009	03:25	AL
Anions	13.40	meq/L	SM1030	0.000	03/30/2009	15:40	SJ
Cations	13.80	meq/L	SM1030	0.000	03/30/2009	15:40	SJ
Balance	1.40	%	SM1030	-10.000	03/30/2009	15:40	SJ
pH	7.80	s. u.	SM4500-H	0.010	03/18/2009	11:19	CM
pH Temperature	14.20	°C	SM4500-H	0.010	03/18/2009	11:19	CM
Settleable Solids	<0.1	mL/L	SM2540-F a	0.100	03/18/2009	14:30	CM
Total Dissolved Solids	755	mg/L	SM2540-C	30.000	03/19/2009	11:45	GK
Total Suspended Solids	8	mg/L	SM2540-D	5.000	03/19/2009	11:45	GK
Chloride, Cl	18	mg/L	EPA 300.0	1.000	03/19/2009	23:43	AL
Alkalinity, mg CaCO ₃ /L (pH 4.5)	408	mg/L	SM2320-B	5.000	03/18/2009	14:20	AL
Carbonate Alkalinity as CaCO ₃	<5	mg/L	SM2320-B	5.000	03/18/2009	14:20	AL
Bicarbonate Alkalinity as CaCO ₃	408	mg/L	SM2320-B	5.000	03/18/2009	14:20	AL

Respectfully submitted,
SGS NORTH AMERICA INC.

Huntington Laboratory



Analysis Report

April 06, 2009

SUNNYSIDE COGENERATION FAC
PO BOX 10
EAST CARBON UT 84520

APR - 9 2009

Page 2 of 2

Client Sample ID: Well 1
Date Sampled: Mar 17, 2009
Date Received: Mar 18, 2009
Product Description: WATER


Sample ID By: Sunnyside Cogeneration Assoc.
Sample Taken At: Well 1
Sample Taken By: Richard Safley
Time Sampled: 1009
Time Received: 1010
Mine: 27
Site: 8
Field - pH: 7.84
Field - Dis. Oxygen: 8.9 MG/L
Field - Flow: 260 GPM
Field - Conductivity: 1200 UMHOS/CM
Field - Temperature: 11.8 DEG. C


Comments: Dissolved Metals Filtered at Lab
pH Expired When Received

SGS Minerals Sample ID: 782-0901004-003

<u>Tests</u>	<u>Result</u>	<u>Unit</u>	<u>Method</u>	<u>REPORTING</u>		<u>ANALYZED</u>	
				<u>LIMIT</u>	<u>DATE</u>	<u>TIME</u>	<u>ANALYST</u>
METALS BY ICP							
Calcium, Ca - Dissolved	71.75	mg/L	EPA 200.7	0.030	03/19/2009	17:39	CM
Iron, Fe - Total	0.94	mg/L	EPA 200.7	0.050	03/24/2009	18:44	CM
Iron, Fe - Dissolved	<0.03	mg/L	EPA 200.7	0.030	03/19/2009	17:39	CM
Magnesium, Mg - Dissolved	64.09	mg/L	EPA 200.7	0.010	03/19/2009	17:39	CM
Manganese, Mn - Total	0.004	mg/L	EPA 200.7	0.002	03/24/2009	18:44	CM
Manganese, Mn - Dissolved	<0.002	mg/L	EPA 200.7	0.002	03/19/2009	17:39	CM
Potassium, K - Dissolved	2.83	mg/L	EPA 200.7	0.140	03/19/2009	17:39	CM
Sodium, Na - Dissolved	111.17	mg/L	EPA 200.7	0.090	03/19/2009	17:39	CM


Respectfully submitted,
SGS NORTH AMERICA, INC.


Huntington Laboratory



APPENDIX B-2 WATER MONITORING

SECOND QUARTER



Sunnyside Cogeneration Associates

P.O. Box 10, East Carbon, Utah 84520 • (435) 888-4476 • Fax (435) 888-2538

July 21, 2009

Darron Haddock
Division of Oil, Gas & Mining
1594 W. North Temple, Suite 1210
Salt Lake City, Utah 84116

Subject: Quarterly Sampling Report
Monitoring Period: April, May, June 2009
DOGM Operational Water Monitoring

Dear Darron:

This letter is to confirm that the quarterly baseline water sampling data and the UPDES DMR data, have been submitted to the DOGM EDI web site. The data is correct and ready to be processed.

Should you have any questions, please contact Rusty Netz or myself at (435)888-4476.

Thank You,

Richard Carter
Agent For
Sunnyside Cogeneration Associates

c.c. Steve Gross
William Rossiter
Maggie Estrada
Paul Shepard
Rusty Netz
Plant File

Sunnyside Cogeneration Facility
Sunnyside, Utah

Field Parameter Data

DOGM Permit Boundry Water Quality Monitoring Plan
Monitoring Period: Second Quarter 2009
Samples taken June 10, 2009

Monitoring Location	Location I.D.	Temp. (C)	pH (su)	SC (umhos)	Dissolved Oxygen (mg/l)	Flow Rate (gpm)	Flow method
Icelander Creek	ICE-1	10.8	8.69	2410	10	3	2
Columbia Dugway Spring	F-2	10.6	8.62	1579	10.2	45	2
Coarse Refuse Seep Source	CRS	NA	NA	NA	NA	NA	NA
Coarse Refuse Seep Boundary	CRB	11.4	8.23	6920	6.5	30	2
Dragerton Well	Well-1	13.4	7.82	1130	6.4	200	4
Borehole B-6	B-6	NW	NW	NW	NW	NW	NW

Notes:

na - no flow

NW - no water present

NW/F - no water present frozen


nd - data is not available due to lack of discharge

1 - Flow rates were measured using a weir.


2 - Flow rates were measured using a calibrated container and stopwatch method.

3 - Flow rates were measured using the floating debris method.

4 - Flow rates were measured using a meter



Analysis Report



Page 1 of 2

SUNNYSIDE COGENERATION FAC
PO BOX 10
EAST CARBON UT 84520

Client Sample ID: CRB
Date Sampled: Jun 10, 2009
Date Received: Jun 11, 2009
Product Description: WATER

Sample ID By: Sunnyside Cogeneration Assoc.
Sample Taken At: CRB
Sample Taken By: Richard S.
Time Sampled: 0957
Time Received: 0940
Mine: 27
Site: 9
Field - pH: 8.23
Field - Dis. Oxygen: 6.5 MG/L
Field - Flow: 30 GPM
Field - Conductivity: 6920 UMHOS/CM
Field - Temperature: 11.4 DEG. C

Comments: Dissolved Metals Filtered at Lab

SGS Minerals Sample ID: 782-0901188-001

Tests	Result	Unit	Method	REPORTING	ANALYZED		
				LIMIT	DATE	TIME	ANALYST
Hardness, mg equivalent CaCO ₃ /L	3334	mg/L	SM2340-B	1.000	06/29/2009	15:28	SJ
Oil and Grease, (HEM)	<5	mg/L	EPA 1664	5.000	06/19/2009	09:30	CM
Anions	103.30	meq/L	SM1030	0.000	06/29/2009	15:27	SJ
Sulfate, SO ₄	4379	mg/L	EPA 300.0	1.000	06/16/2009	15:15	CM
Cations	104.00	meq/L	SM1030	0.000	06/29/2009	15:27	SJ
Balance	0.30	%	SM1030	-10.000	06/29/2009	15:27	SJ
pH	8.05	s. u.	SM4500-H	0.010	06/11/2009	09:57	CM
pH Temperature	17.80	°C	SM4500-H	0.010	06/11/2009	09:57	CM
Settleable Solids	<0.1	mL/L	SM2540-F a	0.100	06/11/2009	12:40	GF
Total Dissolved Solids	7175	mg/L	SM2540-C	30.000	06/11/2009	15:00	CM
Total Suspended Solids	10	mg/L	SM2540-D	5.000	06/11/2009	15:00	CM
Chloride, Cl	180	mg/L	EPA 300.0	1.000	06/12/2009	16:41	CM
Alkalinity, mg CaCO ₃ /L (pH 4.5)	353	mg/L	SM2320-B	5.000	06/16/2009	13:40	AL
Carbonate Alkalinity as CaCO ₃	<5	mg/L	SM2320-B	5.000	06/16/2009	13:40	AL
Bicarbonate Alkalinity as CaCO ₃	353	mg/L	SM2320-B	5.000	06/16/2009	13:40	AL

Respectfully submitted,
SGS NORTH AMERICA INC.

Allen Ludington
Huntington Laboratory



Analysis Report

June 30, 2009

SUNNYSIDE COGENERATION FAC
PO BOX 10
EAST CARBON UT 84520

Page 2 of 2

Client Sample ID: CRB
Date Sampled: Jun 10, 2009
Date Received: Jun 11, 2009
Product Description: WATER


Sample ID By: Sunnyside Cogeneration Assoc.
Sample Taken At: CRB
Sample Taken By: Richard S.
Time Sampled: 0957
Time Received: 0940
Mine: 27
Site: 9
Field - pH: 8.23
Field - Dis. Oxygen: 6.5 MG/L
Field - Flow: 30 GPM
Field - Conductivity: 6920 UMHOS/CM
Field - Temperature: 11.4 DEG. C

Comments: Dissolved Metals Filtered at Lab

SGS Minerals Sample ID: 782-0901188-001


<u>Tests</u>	<u>Result</u>	<u>Unit</u>	<u>Method</u>	<u>REPORTING</u> <u>LIMIT</u>	<u>ANALYZED</u> <u>DATE</u>	<u>TIME</u>	<u>ANALYST</u>
METALS BY ICP							
Calcium, Ca - Dissolved	477.08	mg/L	EPA 200.7	0.030	06/23/2009	16:49	GF
Iron, Fe - Total	0.05	mg/L	EPA 200.7	0.050	06/16/2009	14:51	CM
Iron, Fe - Dissolved	<0.03	mg/L	EPA 200.7	0.030	06/16/2009	22:00	CM
Magnesium, Mg - Dissolved	520.43	mg/L	EPA 200.7	0.010	06/23/2009	16:49	GF
Manganese, Mn - Total	0.006	mg/L	EPA 200.7	0.002	06/16/2009	14:51	CM
Manganese, Mn - Dissolved	0.002	mg/L	EPA 200.7	0.002	06/16/2009	22:00	CM
Potassium, K - Dissolved	48.33	mg/L	EPA 200.7	0.140	06/16/2009	22:00	CM
Sodium, Na - Dissolved	831.56	mg/L	EPA 200.7	0.090	06/26/2009	15:19	GF

Respectfully submitted,
SGS NORTH AMERICA INC.


Huntington Laboratory

SGS North America Inc. | Minerals Services Division
P.O. Box 1020, Huntington, UT 84528 | (435) 653-2311 | (435) 653-2436 | www.us.sgs.com/minerals

Member of the SGS Group



Analysis Report

June 30, 2009

SUNNYSIDE COGENERATION FAC

PO BOX 10
EAST CARBON UT 84520

Page 1 of 2

Client Sample ID: ICE-1
Date Sampled: Jun 10, 2009
Date Received: Jun 11, 2009
Product Description: WATER

Sample ID By: Sunnyside Cogeneration Assoc.
Sample Taken At: ICE-1
Sample Taken By: Richard
Time Sampled: 1024
Time Received: 0940
Mine: 27
Site: 12
Field - pH: 8.69
Field - Dis. Oxygen: 10 MG/L
Field - Flow: 3 GPM
Field - Conductivity: 2410 UMHOS/CM
Field - Temperature: 10.8 DEG. C

Comments: Dissolved Metals Filtered at Lab

SGS Minerals Sample ID: 782-0901188-002

Tests	Result	Unit	Method	REPORTING		ANALYZED	
				LIMIT	DATE	TIME	ANALYST
Hardness, mg equivalent CaCO ₃ /L	1340	mg/L	SM2340-B	1.000	06/29/2009	15:28	SJ
Oil and Grease, (HEM)	<5	mg/L	EPA 1664	5.000	06/19/2009	09:30	CM
Anions	44.00	meq/L	SM1030	0.000	06/29/2009	15:27	SJ
Sulfate, SO ₄	1627	mg/L	EPA 300.0	1.000	06/12/2009	16:41	CM
Cations	44.70	meq/L	SM1030	0.000	06/29/2009	15:27	SJ
Balance	0.80	%	SM1030	-10.000	06/29/2009	15:27	SJ
pH	7.78	s. u.	SM4500-H	0.010	06/11/2009	10:02	CM
pH Temperature	17.50	°C	SM4500-H	0.010	06/11/2009	10:02	CM
Settleable Solids	<0.1	mL/L	SM2540-F a	0.100	06/11/2009	12:40	GF
Total Dissolved Solids	2991	mg/L	SM2540-C	30.000	06/11/2009	15:00	CM
Total Suspended Solids	20	mg/L	SM2540-D	5.000	06/11/2009	15:00	CM
Chloride, Cl	79	mg/L	EPA 300.0	1.000	06/12/2009	16:41	CM
Alkalinity, mg CaCO ₃ /L (pH 4.5)	395	mg/L	SM2320-B	5.000	06/16/2009	13:40	AL
Carbonate Alkalinity as CaCO ₃	<5	mg/L	SM2320-B	5.000	06/16/2009	13:40	AL
Bicarbonate Alkalinity as CaCO ₃	395	mg/L	SM2320-B	5.000	06/16/2009	13:40	AL

Respectfully submitted,
SGS NORTH AMERICA INC.

Allen Huntington
Huntington Laboratory



Analysis Report

June 30, 2009

SUNNYSIDE COGENERATION FAC
PO BOX 10
EAST CARBON UT 84520

Page 2 of 2

Client Sample ID: ICE-1
Date Sampled: Jun 10, 2009
Date Received: Jun 11, 2009
Product Description: WATER

Sample ID By: Sunnyside Cogeneration Assoc.
Sample Taken At: ICE-1
Sample Taken By: Richard
Time Sampled: 1024
Time Received: 0940
Mine: 27
Site: 12
Field - pH: 8.69
Field - Dis. Oxygen: 10 MG/L
Field - Flow: 3 GPM
Field - Conductivity: 2410 UMHOS/CM
Field - Temperature: 10.8 DEG. C


Comments: Dissolved Metals Filtered at Lab

SGS Minerals Sample ID: 782-0901188-002

<u>Tests</u>	<u>Result</u>	<u>Unit</u>	<u>Method</u>	<u>REPORTING</u> <u>LIMIT</u>	<u>ANALYZED</u> <u>DATE</u>	<u>TIME</u>	<u>ANALYST</u>
METALS BY ICP							
Calcium, Ca - Dissolved	180.40	mg/L	EPA 200.7	0.030	06/23/2009	16:49	GF
Iron, Fe - Total	0.35	mg/L	EPA 200.7	0.050	06/16/2009	14:51	CM
Iron, Fe - Dissolved	<0.03	mg/L	EPA 200.7	0.030	06/16/2009	22:00	CM
Magnesium, Mg - Dissolved	216.11	mg/L	EPA 200.7	0.010	06/23/2009	16:49	GF
Manganese, Mn - Total	0.008	mg/L	EPA 200.7	0.002	06/16/2009	14:51	CM
Manganese, Mn - Dissolved	<0.002	mg/L	EPA 200.7	0.002	06/16/2009	22:00	CM
Potassium, K - Dissolved	10.55	mg/L	EPA 200.7	0.140	06/16/2009	22:00	CM
Sodium, Na - Dissolved	406.46	mg/L	EPA 200.7	0.090	06/23/2009	16:49	GF

Respectfully submitted,
SGS NORTH AMERICA INC.

Allen Huntington
Huntington Laboratory



June 30, 2009

Analysis Report

SUNNYSIDE COGENERATION FAC
PO BOX 10
EAST CARBON UT 84520

Page 1 of 2

Client Sample ID: F-2
Date Sampled: Jun 10, 2009
Date Received: Jun 11, 2009
Product Description: WATER


Sample ID By: Sunnyside Cogeneration Assoc.
Sample Taken At: F-2
Sample Taken By: Richard
Time Sampled: 1046
Time Received: 0940
Mine: 27
Site: 11
Field - pH: 8.62
Field - Dis. Oxygen: 10.2 MG/L
Field - Flow: 45 GPM
Field - Conductivity: 1579 UMHOS/CM
Field - Temperature: 10.6 DEG. C

Comments: Dissolved Metals Filtered at Lab

SGS Minerals Sample ID: 782-0901188-003

Tests	Result	Unit	Method	REPORTING	ANALYZED		
				LIMIT	DATE	TIME	ANALYST
Hardness, mg equivalent CaCO ₃ /L	601	mg/L	SM2340-B	1.000	06/29/2009	15:28	SJ
Oil and Grease, (HEM)	<5	mg/L	EPA 1664	5.000	06/19/2009	09:30	CM
Anions	18.90	meq/L	SM1030	0.000	06/29/2009	15:27	SJ
Sulfate, SO ₄	437	mg/L	EPA 300.0	1.000	06/12/2009	16:41	CM
Cations	19.80	meq/L	SM1030	0.000	06/29/2009	15:27	SJ
Balance	2.30	%	SM1030	-10.000	06/29/2009	15:27	SJ
pH	8.42	s. u.	SM4500-H	0.010	06/11/2009	10:05	CM
pH Temperature	17.80	°C	SM4500-H	0.010	06/11/2009	10:05	CM
Settleable Solids	<0.1	mL/L	SM2540-F a	0.100	06/11/2009	12:40	GF
Total Dissolved Solids	1087	mg/L	SM2540-C	30.000	06/11/2009	15:00	CM
Total Suspended Solids	14	mg/L	SM2540-D	5.000	06/11/2009	15:00	CM
Chloride, Cl	30	mg/L	EPA 300.0	1.000	06/12/2009	16:41	CM
Alkalinity, mg CaCO ₃ /L (pH 4.5)	446	mg/L	SM2320-B	5.000	06/16/2009	13:40	AL
Carbonate Alkalinity as CaCO ₃	32	mg/L	SM2320-B	5.000	06/16/2009	13:40	AL
Bicarbonate Alkalinity as CaCO ₃	414	mg/L	SM2320-B	5.000	06/16/2009	13:40	AL

Respectfully submitted,
SGS NORTH AMERICA INC.


Huntington Laboratory



Analysis Report

June 30, 2009

SUNNYSIDE COGENERATION FAC
PO BOX 10
EAST CARBON UT 84520

Page 2 of 2

Client Sample ID: F-2
Date Sampled: Jun 10, 2009
Date Received: Jun 11, 2009
Product Description: WATER


Sample ID By: Sunnyside Cogeneration Assoc.
Sample Taken At: F-2
Sample Taken By: Richard
Time Sampled: 1046
Time Received: 0940
Mine: 27
Site: 11
Field - pH: 8.62
Field - Dis. Oxygen: 10.2 MG/L
Field - Flow: 45 GPM
Field - Conductivity: 1579 UMHOS/CM
Field - Temperature: 10.6 DEG. C


Comments: Dissolved Metals Filtered at Lab

SGS Minerals Sample ID: 782-0901188-003

<u>Tests</u>	<u>Result</u>	<u>Unit</u>	<u>Method</u>	<u>REPORTING</u> <u>LIMIT</u>	<u>ANALYZED</u> <u>DATE</u>	<u>TIME</u>	<u>ANALYST</u>
METALS BY ICP							
Calcium, Ca - Dissolved	82.39	mg/L	EPA 200.7	0.030	06/16/2009	22:00	CM
Iron, Fe - Total	0.88	mg/L	EPA 200.7	0.050	06/16/2009	14:51	CM
Iron, Fe - Dissolved	<0.03	mg/L	EPA 200.7	0.030	06/16/2009	22:00	CM
Magnesium, Mg - Dissolved	96.03	mg/L	EPA 200.7	0.010	06/16/2009	22:00	CM
Manganese, Mn - Total	0.040	mg/L	EPA 200.7	0.002	06/16/2009	14:51	CM
Manganese, Mn - Dissolved	0.013	mg/L	EPA 200.7	0.002	06/16/2009	22:00	CM
Potassium, K - Dissolved	3.29	mg/L	EPA 200.7	0.140	06/16/2009	22:00	CM
Sodium, Na - Dissolved	176.29	mg/L	EPA 200.7	0.090	06/23/2009	16:49	GF

Respectfully submitted,
SGS NORTH AMERICA INC.


Huntington Laboratory



June 30, 2009

Analysis Report

SUNNYSIDE COGENERATION FAC

PO BOX 10
EAST CARBON UT 84520

Page 1 of 2

Client Sample ID: Well-1
Date Sampled: Jun 10, 2009
Date Received: Jun 11, 2009
Product Description: WATER


Sample ID By: Sunnyside Cogeneration Assoc.
Sample Taken At: Well-1
Sample Taken By: Richard S.
Time Sampled: 1100
Time Received: 0940
Mine: 27
Site: 8
Field - pH: 7.82
Field - Dis. Oxygen: 6.4 MG/L
Field - Flow: 200 GPM
Field - Conductivity: 1130 UMHOS/CM
Field - Temperature: 13.4 DEG. C

Comments: Dissolved Metals Filtered at Lab
Raw Bottle Not Obtained At Lab

SGS Minerals Sample ID: 782-0901188-004

Tests	Result	Unit	Method	REPORTING	ANALYZED			
				LIMIT	DATE	TIME	ANALYST	
Hardness, mg equivalent CaCO ₃ /L	451	mg/L	SM2340-B	1.000	06/29/2009	15:28	SJ	
Oil and Grease, (HEM)	<5	mg/L	EPA 1664	5.000	06/19/2009	09:30	CM	
Anions	13.00	meq/L	SM1030	0.000	06/29/2009	15:27	SJ	
Sulfate, SO ₄	224	mg/L	EPA 300.0	1.000	06/12/2009	16:41	CM	
Cations	13.60	meq/L	SM1030	0.000	06/29/2009	15:27	SJ	
Balance	2.00	%	SM1030	-10.000	06/29/2009	15:27	SJ	
pH	7.69	s. u.	SM4500-H	0.010	06/11/2009	10:07	CM	
pH Temperature	17.80	°C	SM4500-H	0.010	06/11/2009	10:07	CM	
Settleable Solids	<0.1	mL/L	SM2540-F a	0.100	06/11/2009	12:40	GF	
Total Dissolved Solids	717	mg/L	SM2540-C	30.000	06/11/2009	15:00	CM	
Total Suspended Solids	<5	mg/L	SM2540-D	5.000	06/11/2009	15:00	CM	
Chloride, Cl	17	mg/L	EPA 300.0	1.000	06/12/2009	16:41	CM	
Alkalinity, mg CaCO ₃ /L (pH 4.5)	395	mg/L	SM2320-B	5.000	06/16/2009	13:40	AL	
Carbonate Alkalinity as CaCO ₃	<5	mg/L	SM2320-B	5.000	06/16/2009	13:40	AL	
Bicarbonate Alkalinity as CaCO ₃	395	mg/L	SM2320-B	5.000	06/16/2009	13:40	AL	

Respectfully submitted,
SGS NORTH AMERICA INC.



Huntington Laboratory

SGS North America Inc. | Minerals Services Division
P.O. Box 1020, Huntington, UT 84528 t (435) 653-2311 f (435) 653-2436 www.us.sgs.com/minerals

Member of the SGS Group



Analysis Report

June 30, 2009

SUNNYSIDE COGENERATION FAC
PO BOX 10
EAST CARBON UT 84520

Page 2 of 2

Client Sample ID: Well-1
Date Sampled: Jun 10, 2009
Date Received: Jun 11, 2009
Product Description: WATER


Sample ID By: Sunnyside Cogeneration Assoc.
Sample Taken At: Well-1
Sample Taken By: Richard S.
Time Sampled: 1100
Time Received: 0940
Mine: 27
Site: 8
Field - pH: 7.82
Field - Dis. Oxygen: 6.4 MG/L
Field - Flow: 200 GPM
Field - Conductivity: 1130 UMHOS/CM
Field - Temperature: 13.4 DEG. C

Comments: Dissolved Metals Filtered at Lab
Raw Bottle Not Obtained At Lab

SGS Minerals Sample ID: 782-0901188-004


<u>Tests</u>	<u>Result</u>	<u>Unit</u>	<u>Method</u>	<u>REPORTING</u>	<u>ANALYZED</u>		
				<u>LIMIT</u>	<u>DATE</u>	<u>TIME</u>	<u>ANALYST</u>
METALS BY ICP							
Calcium, Ca - Dissolved	72.69	mg/L	EPA 200.7	0.030	06/16/2009	22:00	CM
Iron, Fe - Total	0.16	mg/L	EPA 200.7	0.050	06/16/2009	14:51	CM
Iron, Fe - Dissolved	<0.03	mg/L	EPA 200.7	0.030	06/16/2009	22:00	CM
Magnesium, Mg - Dissolved	65.39	mg/L	EPA 200.7	0.010	06/16/2009	22:00	CM
Manganese, Mn - Total	0.002	mg/L	EPA 200.7	0.002	06/16/2009	14:51	CM
Manganese, Mn - Dissolved	<0.002	mg/L	EPA 200.7	0.002	06/16/2009	22:00	CM
Potassium, K - Dissolved	2.76	mg/L	EPA 200.7	0.140	06/16/2009	22:00	CM
Sodium, Na - Dissolved	103.21	mg/L	EPA 200.7	0.090	06/16/2009	22:00	CM

Respectfully submitted,
SGS NORTH AMERICA INC.


Huntington Laboratory


SGS North America Inc. Minerals Services Division
P.O. Box 1020, Huntington, UT 84528 t (435) 653-2311 f (435) 653-2436 www.us.sgs.com/minerals

Member of the SGS Group



APPENDIX B-2 WATER MONITORING

THIRD QUARTER



Sunnyside Cogeneration Associates

P.O. Box 10, East Carbon, Utah 84520 • (435) 888-4476 • Fax (435) 888-2538

October 26, 2009

Darron Haddock
Division of Oil, Gas & Mining
1594 W. North Temple, Suite 1210
Salt Lake City, Utah 84116

Subject: Quarterly Sampling Report
Monitoring Period: July, August, September 2009
DOGM Operational Water Monitoring

Dear Darron:

This letter is to confirm that the quarterly baseline water sampling data and the UPDES DMR data, have been submitted to the DOGM EDI web site. The data is correct and ready to be processed.

Should you have any questions, please contact Rusty Netz or myself at (435)888-4476.

Thank You,

Richard Carter
Agent For
Sunnyside Cogeneration Associates

c.c. Steve Gross
William Rossiter
Maggie Estrada
Paul Shepard
Rusty Netz
Plant File

Sunnyside Cogeneration Facility
Sunnyside, Utah

Field Parameter Data

DOGM Permit Boundry Water Quality Monitoring Plan
Monitoring Period: Second Quarter 2009
Samples taken August 18, 2009

Monitoring Location	Location I.D.	Temp. (C)	pH (su)	SC (umhos)	Dissolved Oxygen (mg/l)	Flow	
						Rate (gpm)	Flow method
Iceland Creek	ICE-1	NW	NW	NW	NW	NW	NW
Columbia Dugway Spring	F-2	12.4	8.32	1761	9	5	2
Coarse Refuse Seep Source	CRS	NA	NA	NA	NA	NA	NA
Coarse Refuse Seep Boundary	CRB	13.9	7.99	7790	8.2	8	2
Dragerton Well	Well-1	16.5	7.69	1264	8.4	200	4
Borehole B-6	B-6	NW	NW	NW	NW	NW	NW

Notes:

na - no flow

NW- no water present

NW/F- no water present frozen

nd - data is not available due to lack of discharge

1 - Flow rates were measured using a weir.

2 - Flow rates were measured using a calibrated container and stopwatch method.

3 - Flow rates were measured using the floating debris method.

4 - Flow rates were measured using a meter



August 26, 2009

Analysis Report

SUNNYSIDE COGENERATION FAC
PO BOX 10
EAST CARBON UT 84520

Page 1 of 2

Client Sample ID: CRB
Date Sampled: Aug 18, 2009
Date Received: Aug 19, 2009
Product Description: WATER

Sample ID By: Sunnyside Cogeneration Assoc.
Sample Taken At: CRB
Sample Taken By: Richard Safely
Time Sampled: 0830
Time Received: 1000
Mine: 27
Site: 9
Field - pH: 7.99
Field - Dis. Oxygen: 8.2 MG/L
Field - Flow: 8 GPM
Field - Conductivity: 7790 UMHOS/CM
Field - Temperature: 13.9 DEG. C

Comments: Dissolved Metals Filtered at Lab
pH Expired when recieved

SGS Minerals Sample ID: 782-0901442-001

Tests	Result	Unit	Method	REPORTING	ANALYZED		
				LIMIT	DATE	TIME	ANALYST
Hardness, mg equivalent CaCO ₃ /L	3773	mg/L	SM2340-B	1.000	08/26/2009	09:23	AL
Oil and Grease, (HEM)	<5	mg/L	EPA 1664	5.000	08/24/2009	09:30	CM
Sulfate, SO ₄	4896	mg/L	EPA 300.0	1.000	08/20/2009	14:44	CM
Anions	115.00	meq/L	SM1030	0.000	08/26/2009	09:23	AL
Cations	124.70	meq/L	SM1030	0.000	08/26/2009	09:23	AL
Balance	4.10	%	SM1030	-10.000	08/26/2009	09:23	AL
pH	8.13	s. u.	SM4500-H	0.010	08/19/2009	10:55	CM
pH Temperature	18.30	°C	SM4500-H	0.010	08/19/2009	10:55	CM
Settleable Solids	<0.1	mL/L	SM2540-F a	0.100	08/19/2009	11:00	GF
Total Dissolved Solids	8478	mg/L	SM2540-C	30.000	08/20/2009	15:00	GF
Total Suspended Solids	<5	mg/L	SM2540-D	5.000	08/20/2009	15:00	GF
Chloride, Cl	200	mg/L	EPA 300.0	1.000	08/19/2009	17:17	CM
Alkalinity, mg CaCO ₃ /L (pH 4.5)	369	mg/L	SM2320-B	5.000	08/19/2009	13:00	CM
Carbonate Alkalinity as CaCO ₃	<5	mg/L	SM2320-B	5.000	08/19/2009	13:00	CM
Bicarbonate Alkalinity as CaCO ₃	369	mg/L	SM2320-B	5.000	08/19/2009	13:00	CM

Respectfully submitted,
SGS NORTH AMERICA INC.

Allen Huntington
Huntington Laboratory

SGS North America Inc. | Minerals Services Division
P.O. Box 1020, Huntington, UT 84528 t (435) 653-2311 f (435) 653-2436 www.us.sgs.com/minerals

Member of the SGS Group



Analysis Report

August 26, 2009

SUNNYSIDE COGENERATION FAC
PO BOX 10
EAST CARBON UT 84520

Page 2 of 2

Client Sample ID: CRB
Date Sampled: Aug 18, 2009
Date Received: Aug 19, 2009
Product Description: WATER

Sample ID By: Sunnyside Cogeneration Assoc.
Sample Taken At: CRB
Sample Taken By: Richard Safely
Time Sampled: 0830
Time Received: 1000
Mine: 27
Site: 9
Field - pH: 7.99
Field - Dis. Oxygen: 8.2 MG/L
Field - Flow: 8 GPM
Field - Conductivity: 7790 UMHOS/CM
Field - Temperature: 13.9 DEG. C


Comments: Dissolved Metals Filtered at Lab
pH Expired when recieved

SGS Minerals Sample ID: 782-0901442-001

<u>Tests</u>	<u>Result</u>	<u>Unit</u>	<u>Method</u>	<u>LIMIT</u>	<u>DATE</u>	<u>TIME</u>	<u>ANALYST</u>
METALS BY ICP							
Calcium, Ca - Dissolved	495.36	mg/L	EPA 200.7	0.030	08/25/2009	15:51	CM
Iron, Fe - Total	<0.05	mg/L	EPA 200.7	0.050	08/25/2009	12:41	CM
Iron, Fe - Dissolved	<0.03	mg/L	EPA 200.7	0.030	08/25/2009	15:51	CM
Magnesium, Mg - Dissolved	615.74	mg/L	EPA 200.7	0.010	08/25/2009	15:51	CM
Manganese, Mn - Total	<0.002	mg/L	EPA 200.7	0.002	08/25/2009	12:41	CM
Manganese, Mn - Dissolved	<0.002	mg/L	EPA 200.7	0.002	08/25/2009	15:51	CM
Potassium, K - Dissolved	59.14	mg/L	EPA 200.7	0.140	08/25/2009	15:51	CM
Sodium, Na - Dissolved	1099.30	mg/L	EPA 200.7	0.090	08/25/2009	15:51	CM

Respectfully submitted,
SGS NORTH AMERICA INC.

Allen Huntington
Huntington Laboratory



Analysis Report

August 26, 2009

SUNNYSIDE COGENERATION FAC
PO BOX 10
EAST CARBON UT 84520

Page 1 of 2

Client Sample ID: F-2
Date Sampled: Aug 18, 2009
Date Received: Aug 19, 2009
Product Description: WATER


Sample ID By: Sunnyside Cogeneration Assoc.
Sample Taken At: F-2
Sample Taken By: Richard Safely
Time Sampled: 0900
Time Received: 1000
Mine: 27
Site: 11
Field - pH: 8.32
Field - Dis. Oxygen: 9.0 MG/L
Field - Flow: 5 GPM
Field - Conductivity: 1761 UMHOS/CM
Field - Temperature: 12.4 DEG. C

Comments: Dissolved Metals Filtered at Lab
pH Expired when recieved

SGS Minerals Sample ID: 782-0901442-002

Tests	Result	Unit	Method	REPORTING		ANALYZED	
				LIMIT	DATE	TIME	ANALYST
Hardness, mg equivalent CaCO ₃ /L	664	mg/L	SM2340-B	1.000	08/26/2009	09:23	AL
Oil and Grease, (HEM)	<5	mg/L	EPA 1664	5.000	08/24/2009	09:30	CM
Sulfate, SO ₄	472	mg/L	EPA 300.0	1.000	08/19/2009	17:17	CM
Anions	21.40	meq/L	SM1030	0.000	08/26/2009	09:23	AL
Cations	22.10	meq/L	SM1030	0.000	08/26/2009	09:23	AL
Balance	1.60	%	SM1030	-10.000	08/26/2009	09:23	AL
pH	8.42	s. u.	SM4500-H	0.010	08/19/2009	10:57	CM
pH Temperature	18.30	°C	SM4500-H	0.010	08/19/2009	10:57	CM
Settleable Solids	<0.1	mL/L	SM2540-F a	0.100	08/19/2009	11:00	GF
Total Dissolved Solids	1283	mg/L	SM2540-C	30.000	08/20/2009	15:00	GF
Total Suspended Solids	6	mg/L	SM2540-D	5.000	08/20/2009	15:00	GF
Chloride, Cl	36	mg/L	EPA 300.0	1.000	08/19/2009	17:17	CM
Alkalinity, mg CaCO ₃ /L (pH 4.5)	529	mg/L	SM2320-B	5.000	08/19/2009	13:00	CM
Carbonate Alkalinity as CaCO ₃	16	mg/L	SM2320-B	5.000	08/19/2009	13:00	CM
Bicarbonate Alkalinity as CaCO ₃	512	mg/L	SM2320-B	5.000	08/19/2009	13:00	CM

Respectfully submitted,
SGS NORTH AMERICA INC.


Huntington Laboratory



Analysis Report

August 26, 2009

SUNNYSIDE COGENERATION FAC
PO BOX 10
EAST CARBON UT 84520

Page 2 of 2

Client Sample ID: F-2
Date Sampled: Aug 18, 2009
Date Received: Aug 19, 2009
Product Description: WATER


Sample ID By: Sunnyside Cogeneration Assoc.
Sample Taken At: F-2
Sample Taken By: Richard Safely
Time Sampled: 0900
Time Received: 1000
Mine: 27
Site: 11
Field - pH: 8.32
Field - Dis. Oxygen: 9.0 MG/L
Field - Flow: 5 GPM
Field - Conductivity: 1761 UMHOS/CM
Field - Temperature: 12.4 DEG. C

Comments: Dissolved Metals Filtered at Lab
pH Expired when recieved

SGS Minerals Sample ID: 782-0901442-002

<u>Tests</u>	<u>Result</u>	<u>Unit</u>	<u>Method</u>	<u>REPORTING</u>	<u>ANALYZED</u>		
				<u>LIMIT</u>	<u>DATE</u>	<u>TIME</u>	<u>ANALYST</u>
METALS BY ICP							
Calcium, Ca - Dissolved	83.49	mg/L	EPA 200.7	0.030	08/25/2009	15:51	CM
Iron, Fe - Total	0.14	mg/L	EPA 200.7	0.050	08/25/2009	12:41	CM
Iron, Fe - Dissolved	<0.03	mg/L	EPA 200.7	0.030	08/25/2009	15:51	CM
Magnesium, Mg - Dissolved	110.50	mg/L	EPA 200.7	0.010	08/25/2009	15:51	CM
Manganese, Mn - Total	0.019	mg/L	EPA 200.7	0.002	08/25/2009	12:41	CM
Manganese, Mn - Dissolved	0.011	mg/L	EPA 200.7	0.002	08/25/2009	15:51	CM
Potassium, K - Dissolved	2.75	mg/L	EPA 200.7	0.140	08/25/2009	15:51	CM
Sodium, Na - Dissolved	202.14	mg/L	EPA 200.7	0.090	08/25/2009	15:51	CM

Respectfully submitted,
SGS NORTH AMERICA INC.


Huntington Laboratory



Analysis Report

SUNNYSIDE COGENERATION FAC
PO BOX 10
EAST CARBON UT 84520

Page 1 of 2

Client Sample ID: Well #1
Date Sampled: Aug 18, 2009
Date Received: Aug 19, 2009
Product Description: WATER

Sample ID By: Sunnyside Cogeneration Assoc.
Sample Taken At: Well #1
Sample Taken By: Richard Safely
Time Sampled: 0920
Time Received: 1000
Mine: 27
Site: 8
Field - pH: 7.69
Field - Dis. Oxygen: 8.4 MG/L
Field - Flow: 200 GPM
Field - Conductivity: 1264 UMHOS/CM
Field - Temperature: 16.5 DEG. C

Comments: Dissolved Metals Filtered at Lab
pH Expired when recieved

SGS Minerals Sample ID: 782-0901442-003

Tests	Result	Unit	Method	REPORTING	ANALYZED		
				LIMIT	DATE	TIME	ANALYST
Hardness, mg equivalent CaCO ₃ /L	508	mg/L	SM2340-B	1.000	08/26/2009	09:23	AL
Oil and Grease, (HEM)	<5	mg/L	EPA 1664	5.000	08/24/2009	09:30	CM
Sulfate, SO ₄	290	mg/L	EPA 300.0	1.000	08/19/2009	17:17	CM
Anions	14.91	meq/L	SM1030	0.000	08/26/2009	09:23	AL
Cations	15.39	meq/L	SM1030	0.000	08/26/2009	09:23	AL
Balance	1.57	%	SM1030	-10.000	08/26/2009	09:23	AL
pH	8.02	s. u.	SM4500-H	0.010	08/19/2009	10:59	CM
pH Temperature	19.20	°C	SM4500-H	0.010	08/19/2009	10:59	CM
Settleable Solids	<0.1	mL/L	SM2540-F a	0.100	08/19/2009	11:00	GF
Total Dissolved Solids	867	mg/L	SM2540-C	30.000	08/20/2009	15:00	GF
Total Suspended Solids	<5	mg/L	SM2540-D	5.000	08/20/2009	15:00	GF
Chloride, Cl	45	mg/L	EPA 300.0	1.000	08/19/2009	17:17	CM
Alkalinity, mg CaCO ₃ /L (pH 4.5)	380	mg/L	SM2320-B	5.000	08/19/2009	13:00	CM
Carbonate Alkalinity as CaCO ₃	<5	mg/L	SM2320-B	5.000	08/19/2009	13:00	CM
Bicarbonate Alkalinity as CaCO ₃	380	mg/L	SM2320-B	5.000	08/19/2009	13:00	CM

Respectfully submitted,
SGS NORTH AMERICA INC.

Allen Huntington
Huntington Laboratory



Analysis Report

August 26, 2009

SUNNYSIDE COGENERATION FAC
PO BOX 10
EAST CARBON UT 84520

Page 2 of 2

Client Sample ID: Well #1
Date Sampled: Aug 18, 2009
Date Received: Aug 19, 2009
Product Description: WATER


Sample ID By: Sunnyside Cogeneration Assoc.
Sample Taken At: Well #1
Sample Taken By: Richard Safely
Time Sampled: 0920
Time Received: 1000
Mine: 27
Site: 8
Field - pH: 7.69
Field - Dis. Oxygen: 8.4 MG/L
Field - Flow: 200 GPM
Field - Conductivity: 1264 UMHOS/CM
Field - Temperature: 16.5 DEG. C

Comments: Dissolved Metals Filtered at Lab
pH Expired when recieved

SGS Minerals Sample ID: 782-0901442-003


<u>Tests</u>	<u>Result</u>	<u>Unit</u>	<u>Method</u>	<u>REPORTING</u>	<u>ANALYZED</u>		
				<u>LIMIT</u>	<u>DATE</u>	<u>TIME</u>	<u>ANALYST</u>
METALS BY ICP							
Calcium, Ca - Dissolved	64.64	mg/L	EPA 200.7	0.030	08/25/2009	15:51	CM
Iron, Fe - Total	0.14	mg/L	EPA 200.7	0.050	08/25/2009	12:41	CM
Iron, Fe - Dissolved	<0.03	mg/L	EPA 200.7	0.030	08/25/2009	15:51	CM
Magnesium, Mg - Dissolved	84.06	mg/L	EPA 200.7	0.010	08/25/2009	15:51	CM
Manganese, Mn - Total	0.003	mg/L	EPA 200.7	0.002	08/25/2009	12:41	CM
Manganese, Mn - Dissolved	0.003	mg/L	EPA 200.7	0.002	08/25/2009	15:51	CM
Potassium, K - Dissolved	2.34	mg/L	EPA 200.7	0.140	08/25/2009	15:51	CM
Sodium, Na - Dissolved	119.21	mg/L	EPA 200.7	0.090	08/25/2009	15:51	CM

Respectfully submitted,
SGS NORTH AMERICA INC.


Huntington Laboratory


SGS North America Inc. Minerals Services Division
P.O. Box 1020, Huntington, UT 84528 t (435) 653-2311 f (435) 653-2436 www.us.sgs.com/minerals

Member of the SGS Group



APPENDIX B-2 WATER MONITORING

FOURTH QUARTER



Sunnyside Cogeneration Associates

P.O. Box 10, East Carbon, Utah 84520 • (435) 888-4476 • Fax (435) 888-2538

January 15, 2010

Darron Haddock
Division of Oil, Gas & Mining
1594 W. North Temple, Suite 1210
Salt Lake City, Utah 84116

Subject: Quarterly Sampling Report
Monitoring Period: October, November, December 2009
DOGM Operational Water Monitoring

Dear Darron:

This letter is to confirm that the quarterly baseline water sampling data and the UPDES DMR data, have been submitted to the DOGM EDI web site. The data is correct and ready to be processed.

Should you have any questions, please contact Rusty Netz or myself at (435)888-4476.

Thank You,


Richard Carter
Agent For
Sunnyside Cogeneration Associates

c.c. Steve Gross
William Rossiter
Maggie Estrada
Paul Shepard
Rusty Netz
Plant File



December 16, 2009

Analysis Report



Page 1 of 2

SUNNYSIDE COGENERATION FAC
PO BOX 10
EAST CARBON UT 84520

Client Sample ID: CRB
Date Sampled: Dec 2, 2009
Date Received: Dec 3, 2009
Product Description: WATER

Sample ID By: Sunnyside Cogeneration Assoc.
Sample Taken At: CRB
Sample Taken By: Rusty Netz
Time Sampled: 0900
Time Received: 1050
Mine: 27
Site: 9
Field - pH: 7.98 pH
Field - Dis. Oxygen: 10.5 MG/L
Field - Flow: 2 GPM
Field - Conductivity: 6650 UMHOS/CM
Field - Temperature: 2.0 DEG. C

Comments: Dissolved Metals Filtered at Lab
Sulfuric bottle preserved at lab
pH expired when received

SGS Minerals Sample ID: 782-0901803-001

Tests	Result	Unit	Method	REPORTING	ANALYZED		
				LIMIT	DATE	TIME	ANALYST
Hardness, mg equivalent CaCO ₃ /L	3242	mg/L	SM2340-B	1.000	12/16/2009	09:26	AL
Oil and Grease, (HEM)	<5	mg/L	EPA 1664	5.000	12/14/2009	09:30	CM
Acidity	15	mg/L	D1067	5.000	12/08/2009	13:10	CM
Anions	101.37	meq/L	SM1030	0.000	12/16/2009	09:26	AL
Cations	104.17	meq/L	SM1030	0.000	12/16/2009	09:26	AL
Balance	1.36	%	SM1030	-10.000	12/16/2009	09:26	AL
Nitrite	<0.05	mg/L	EPA 300.0	0.050	12/03/2009	19:57	CM
Nitrate	0.67	mg/L	EPA 300.0	0.050	12/03/2009	19:57	CM
Ortho-Phosphate-P	<0.05	mg/L	EPA 300.0	0.050	12/03/2009	19:57	CM
Sulfate, SO ₄	4252	mg/L	EPA 300.0	1.000	12/07/2009	22:51	CM
Nitrogen, Ammonia	<0.1	mg/L	SM4500-B-D	0.100	12/11/2009	08:00	CM
Conductivity	6930	µmhos/cm	SM2510	0.100	12/03/2009	11:30	CM
pH	8.19	s. u.	SM4500-H	0.010	12/03/2009	11:55	CM
pH Temperature	15.00	°C	SM4500-H	0.010	12/03/2009	11:55	CM
Settleable Solids	<0.1	mL/L	SM2540-F a	0.100	12/03/2009	14:00	AL
Total Dissolved Solids	7326	mg/L	SM2540-C	30.000	12/07/2009	14:50	CM
Total Suspended Solids	8	mg/L	SM2540-D	5.000	12/07/2009	14:50	CM
Chloride, Cl	187	mg/L	EPA 300.0	1.000	12/03/2009	19:57	CM
Alkalinity, mg CaCO ₃ /L (pH 4.5)	378	mg/L	SM2320-B	5.000	12/04/2009	09:30	CM
Carbonate Alkalinity as CaCO ₃	<5	mg/L	SM2320-B	5.000	12/04/2009	09:30	CM
Bicarbonate Alkalinity as CaCO ₃	378	mg/L	SM2320-B	5.000	12/04/2009	09:30	CM

Respectfully submitted,
SGS NORTH AMERICA INC.

Huntington Laboratory



Analysis Report

SUNNYSIDE COGENERATION FAC
PO BOX 10
EAST CARBON UT 84520

Page 2 of 2

Client Sample ID: CRB
Date Sampled: Dec 2, 2009
Date Received: Dec 3, 2009
Product Description: WATER


Sample ID By: Sunnyside Cogeneration Assoc.
Sample Taken At: CRB
Sample Taken By: Rusty Netz
Time Sampled: 0900
Time Received: 1050
Mine: 27
Site: 9
Field - pH: 7.98 pH
Field - Dis. Oxygen: 10.5 MG/L
Field - Flow: 2 GPM
Field - Conductivity: 6650 UMHOS/CM
Field - Temperature: 2.0 DEG. C

Comments: Dissolved Metals Filtered at Lab
Sulfuric bottle preserved at lab
pH expired when received

SGS Minerals Sample ID: 782-0901803-001

<u>Tests</u>	<u>Result</u>	<u>Unit</u>	<u>Method</u>	REPORTING	ANALYZED		
				<u>LIMIT</u>	<u>DATE</u>	<u>TIME</u>	<u>ANALYST</u>
METALS BY ICP							
Molybdenum, Mo - Dissolved	<0.005	mg/L	EPA 200.7	0.005	12/10/2009	14:04	CM
Aluminum, Al - Dissolved	<0.03	mg/L	EPA 200.7	0.030	12/10/2009	14:04	CM
Arsenic, As - Dissolved	<0.01	mg/L	EPA 200.7	0.010	12/10/2009	14:04	CM
Boron, B - Dissolved	1.88	mg/L	EPA 200.7	0.010	12/10/2009	14:04	CM
Cadmium, Cd - Dissolved	<0.001	mg/L	EPA 200.7	0.001	12/10/2009	14:04	CM
Calcium, Ca - Dissolved	459.58	mg/L	EPA 200.7	0.030	12/10/2009	14:04	CM
Copper, Cu - Dissolved	0.02	mg/L	EPA 200.7	0.010	12/15/2009	15:05	CM
Iron, Fe - Total	<0.05	mg/L	EPA 200.7	0.050	12/08/2009	16:20	CM
Iron, Fe - Dissolved	<0.03	mg/L	EPA 200.7	0.030	12/10/2009	14:04	CM
Lead, Pb - Dissolved	<0.01	mg/L	EPA 200.7	0.010	12/10/2009	14:04	CM
Magnesium, Mg - Dissolved	508.72	mg/L	EPA 200.7	0.010	12/10/2009	14:04	CM
Manganese, Mn - Total	<0.002	mg/L	EPA 200.7	0.002	12/08/2009	16:20	CM
Manganese, Mn - Dissolved	<0.002	mg/L	EPA 200.7	0.002	12/10/2009	14:04	CM
Potassium, K - Dissolved	44.04	mg/L	EPA 200.7	0.140	12/10/2009	14:04	CM
Selenium, Se - Dissolved	<0.02	mg/L	EPA 200.7	0.020	12/10/2009	14:04	CM
Sodium, Na - Dissolved	879.61	mg/L	EPA 200.7	0.090	12/10/2009	14:04	CM
Zinc, Zn - Dissolved	<0.004	mg/L	EPA 200.7	0.004	12/10/2009	14:04	CM

Respectfully submitted,
SGS NORTH AMERICA INC.


Huntington Laboratory

SGS North America Inc. Minerals Services Division
P.O. Box 1020, Huntington, UT 84528 t (435) 653-2311 f (435) 653-2436 www.us.sgs.com/minerals



Analysis Report

December 16, 2009

SUNNYSIDE COGENERATION FAC
PO BOX 10
EAST CARBON UT 84520

Page 1 of 2

Client Sample ID: F2
Date Sampled: Dec 2, 2009
Date Received: Dec 3, 2009
Product Description: WATER


Sample ID By: Sunnyside Cogeneration Assoc.
Sample Taken At: F2
Sample Taken By: Rusty Netz
Time Sampled: 0940
Time Received: 1050
Mine: 27
Site: 11
Field - pH: 8.39 pH
Field - Dis. Oxygen: 11 MG/L
Field - Flow: 8 GPM
Field - Conductivity: 1698 UMHOS/CM
Field - Temperature: 1.5 DEG. C


Comments: Dissolved Metals Filtered at Lab
Sulfuric bottle preserved at lab
pH expired when received

SGS Minerals Sample ID: 782-0901803-002

Tests	Result	Unit	Method	REPORTING	ANALYZED		
				LIMIT	DATE	TIME	ANALYST
Hardness, mg equivalent CaCO ₃ /L	650	mg/L	SM2340-B	1.000	12/16/2009	09:26	AL
Oil and Grease, (HEM)	<5	mg/L	EPA 1664	5.000	12/14/2009	09:30	CM
Acidity	<5	mg/L	D1067	5.000	12/08/2009	13:10	CM
Anions	21.32	meq/L	SM1030	0.000	12/16/2009	09:26	AL
Cations	21.40	meq/L	SM1030	0.000	12/16/2009	09:26	AL
Balance	0.19	%	SM1030	-10.000	12/16/2009	09:26	AL
Nitrite	<0.05	mg/L	EPA 300.0	0.050	12/03/2009	19:57	CM
Nitrate	0.17	mg/L	EPA 300.0	0.050	12/03/2009	19:57	CM
Ortho-Phosphate-P	<0.05	mg/L	EPA 300.0	0.050	12/03/2009	19:57	CM
Sulfate, SO ₄	515	mg/L	EPA 300.0	1.000	12/07/2009	22:51	CM
Nitrogen, Ammonia	<0.1	mg/L	SM4500-B-D	0.100	12/11/2009	08:00	CM
Conductivity	1721	µmhos/cm	SM2510	0.100	12/03/2009	11:30	CM
pH	8.45	s. u.	SM4500-H	0.010	12/03/2009	11:57	CM
pH Temperature	14.80	°C	SM4500-H	0.010	12/03/2009	11:57	CM
Settleable Solids	<0.1	mL/L	SM2540-F a	0.100	12/03/2009	14:00	AL
Total Dissolved Solids	1258	mg/L	SM2540-C	30.000	12/07/2009	14:50	CM
Total Suspended Solids	6	mg/L	SM2540-D	5.000	12/07/2009	14:50	CM
Chloride, Cl	38	mg/L	EPA 300.0	1.000	12/03/2009	19:57	CM
Alkalinity, mg CaCO ₃ /L (pH 4.5)	477	mg/L	SM2320-B	5.000	12/04/2009	09:30	CM
Carbonate Alkalinity as CaCO ₃	27	mg/L	SM2320-B	5.000	12/04/2009	09:30	CM
Bicarbonate Alkalinity as CaCO ₃	449	mg/L	SM2320-B	5.000	12/04/2009	09:30	CM

Respectfully submitted,
SGS NORTH AMERICA INC.


Huntington Laboratory



Analysis Report

December 16, 2009

SUNNYSIDE COGENERATION FAC

PO BOX 10
EAST CARBON UT 84520

Page 2 of 2

Client Sample ID: F2
Date Sampled: Dec 2, 2009
Date Received: Dec 3, 2009
Product Description: WATER


Sample ID By: Sunnyside Cogeneration Assoc.
Sample Taken At: F2
Sample Taken By: Rusty Netz
Time Sampled: 0940
Time Received: 1050
Mine: 27
Site: 11
Field - pH: 8.39 pH
Field - Dis. Oxygen: 11 MG/L
Field - Flow: 8 GPM
Field - Conductivity: 1698 UMHOS/CM
Field - Temperature: 1.5 DEG. C

Comments: Dissolved Metals Filtered at Lab
Sulfuric bottle preserved at lab
pH expired when received

SGS Minerals Sample ID: 782-0901803-002

<u>Tests</u>	<u>Result</u>	<u>Unit</u>	<u>Method</u>	REPORTING	ANALYZED		
				<u>LIMIT</u>	<u>DATE</u>	<u>TIME</u>	<u>ANALYST</u>
METALS BY ICP							
Molybdenum, Mo - Dissolved	<0.005	mg/L	EPA 200.7	0.005	12/10/2009	14:04	CM
Aluminum, Al - Dissolved	<0.03	mg/L	EPA 200.7	0.030	12/10/2009	14:04	CM
Arsenic, As - Dissolved	<0.01	mg/L	EPA 200.7	0.010	12/10/2009	14:04	CM
Boron, B - Dissolved	0.18	mg/L	EPA 200.7	0.010	12/10/2009	14:04	CM
Cadmium, Cd - Dissolved	<0.001	mg/L	EPA 200.7	0.001	12/10/2009	14:04	CM
Calcium, Ca - Dissolved	85.48	mg/L	EPA 200.7	0.030	12/10/2009	14:04	CM
Copper, Cu - Dissolved	0.01	mg/L	EPA 200.7	0.010	12/15/2009	15:05	CM
Iron, Fe - Total	0.39	mg/L	EPA 200.7	0.050	12/08/2009	16:20	CM
Iron, Fe - Dissolved	<0.03	mg/L	EPA 200.7	0.030	12/10/2009	14:04	CM
Lead, Pb - Dissolved	<0.01	mg/L	EPA 200.7	0.010	12/10/2009	14:04	CM
Magnesium, Mg - Dissolved	105.89	mg/L	EPA 200.7	0.010	12/10/2009	14:04	CM
Manganese, Mn - Total	0.030	mg/L	EPA 200.7	0.002	12/08/2009	16:20	CM
Manganese, Mn - Dissolved	0.016	mg/L	EPA 200.7	0.002	12/10/2009	14:04	CM
Potassium, K - Dissolved	2.76	mg/L	EPA 200.7	0.140	12/10/2009	14:04	CM
Selenium, Se - Dissolved	<0.02	mg/L	EPA 200.7	0.020	12/10/2009	14:04	CM
Sodium, Na - Dissolved	192.00	mg/L	EPA 200.7	0.090	12/10/2009	14:04	CM
Zinc, Zn - Dissolved	0.004	mg/L	EPA 200.7	0.004	12/10/2009	14:04	CM

Respectfully submitted,
SGS NORTH AMERICA INC.


Huntington Laboratory



Analysis Report

December 16, 2009

SUNNYSIDE COGENERATION FAC

PO BOX 10
EAST CARBON UT 84520

Page 1 of 2

Client Sample ID: Well #1
Date Sampled: Dec 2, 2009
Date Received: Dec 3, 2009
Product Description: WATER

Sample ID By: Sunnyside Cogeneration Assoc.
Sample Taken At: Well #1
Sample Taken By: Rusty Netz
Time Sampled: 1000
Time Received: 1050
Mine: 27
Site: 8
Field - pH: 7.54 pH
Field - Dis. Oxygen: 11 MG/L
Field - Flow: 190 GPM
Field - Conductivity: 1249 UMHOS/CM
Field - Temperature: 5.9 DEG. C

Comments: Dissolved Metals Filtered at Lab
Sulfuric bottle preserved at lab
pH expired when received

SGS Minerals Sample ID: 782-0901803-003

Tests	Result	Unit	Method	REPORTING	ANALYZED		
				LIMIT	DATE	TIME	ANALYST
Hardness, mg equivalent CaCO ₃ /L	481	mg/L	SM2340-B	1.000	12/16/2009	09:26	AL
Oil and Grease, (HEM)	<5	mg/L	EPA 1664	5.000	12/14/2009	09:30	CM
Acidity	20	mg/L	D1067	5.000	12/08/2009	13:10	CM
Anions	14.59	meq/L	SM1030	0.000	12/16/2009	09:26	AL
Cations	14.71	meq/L	SM1030	0.000	12/16/2009	09:26	AL
Balance	0.40	%	SM1030	-10.000	12/16/2009	09:26	AL
Nitrite	<0.05	mg/L	EPA 300.0	0.050	12/03/2009	19:57	CM
Nitrate	1.16	mg/L	EPA 300.0	0.050	12/03/2009	19:57	CM
Ortho-Phosphate-P	<0.05	mg/L	EPA 300.0	0.050	12/03/2009	19:57	CM
Sulfate, SO ₄	274	mg/L	EPA 300.0	1.000	12/03/2009	19:57	CM
Nitrogen, Ammonia	<0.1	mg/L	SM4500-B-D	0.100	12/11/2009	08:00	CM
Conductivity	1251	µmhos/cm	SM2510	0.100	12/03/2009	11:30	CM
pH	7.87	s. u.	SM4500-H	0.010	12/03/2009	11:59	CM
pH Temperature	14.80	°C	SM4500-H	0.010	12/03/2009	11:59	CM
Settleable Solids	<0.1	mL/L	SM2540-F a	0.100	12/03/2009	14:00	AL
Total Dissolved Solids	822	mg/L	SM2540-C	30.000	12/07/2009	14:50	CM
Total Suspended Solids	<5	mg/L	SM2540-D	5.000	12/07/2009	14:50	CM
Chloride, Cl	38	mg/L	EPA 300.0	1.000	12/03/2009	19:57	CM
Alkalinity, mg CaCO ₃ /L (pH 4.5)	391	mg/L	SM2320-B	5.000	12/04/2009	09:30	CM
Carbonate Alkalinity as CaCO ₃	<5	mg/L	SM2320-B	5.000	12/04/2009	09:30	CM
Bicarbonate Alkalinity as CaCO ₃	391	mg/L	SM2320-B	5.000	12/04/2009	09:30	CM

Respectfully submitted,
SGS NORTH AMERICA INC.

Huntington Laboratory

SGS North America Inc.

Minerals Services Division

P.O. Box 1020, Huntington, UT 84528 t(435) 653-2311 f(435) 653-2436 www.us.sgs.com/minerals

Member of the SGS Group



Analysis Report

December 16, 2009

SUNNYSIDE COGENERATION FAC
PO BOX 10
EAST CARBON UT 84520

Page 2 of 2

Client Sample ID: Well #1
Date Sampled: Dec 2, 2009
Date Received: Dec 3, 2009
Product Description: WATER

Sample ID By: Sunnyside Cogeneration Assoc.
Sample Taken At: Well #1
Sample Taken By: Rusty Netz
Time Sampled: 1000
Time Received: 1050
Mine: 27
Site: 8
Field - pH: 7.54 pH
Field - Dis. Oxygen: 11 MG/L
Field - Flow: 190 GPM
Field - Conductivity: 1249 UMHOS/CM
Field - Temperature: 5.9 DEG. C


Comments: Dissolved Metals Filtered at Lab
Sulfuric bottle preserved at lab
pH expired when received

SGS Minerals Sample ID: 782-0901803-003

Tests	Result	Unit	Method	REPORTING	ANALYZED		
				LIMIT	DATE	TIME	ANALYST
METALS BY ICP							
Molybdenum, Mo - Dissolved	<0.005	mg/L	EPA 200.7	0.005	12/10/2009	14:04	CM
Aluminum, Al - Dissolved	<0.03	mg/L	EPA 200.7	0.030	12/10/2009	14:04	CM
Arsenic, As - Dissolved	<0.01	mg/L	EPA 200.7	0.010	12/10/2009	14:04	CM
Boron, B - Dissolved	0.19	mg/L	EPA 200.7	0.010	12/10/2009	14:04	CM
Cadmium, Cd - Dissolved	<0.001	mg/L	EPA 200.7	0.001	12/10/2009	14:04	CM
Calcium, Ca - Dissolved	67.17	mg/L	EPA 200.7	0.030	12/10/2009	14:04	CM
Copper, Cu - Dissolved	0.01	mg/L	EPA 200.7	0.010	12/15/2009	15:05	CM
Iron, Fe - Total	0.08	mg/L	EPA 200.7	0.050	12/08/2009	16:20	CM
Iron, Fe - Dissolved	<0.03	mg/L	EPA 200.7	0.030	12/10/2009	14:04	CM
Lead, Pb - Dissolved	<0.01	mg/L	EPA 200.7	0.010	12/10/2009	14:04	CM
Magnesium, Mg - Dissolved	76.18	mg/L	EPA 200.7	0.010	12/10/2009	14:04	CM
Manganese, Mn - Total	0.004	mg/L	EPA 200.7	0.002	12/08/2009	16:20	CM
Manganese, Mn - Dissolved	0.004	mg/L	EPA 200.7	0.002	12/10/2009	14:04	CM
Potassium, K - Dissolved	2.64	mg/L	EPA 200.7	0.140	12/10/2009	14:04	CM
Selenium, Se - Dissolved	<0.02	mg/L	EPA 200.7	0.020	12/10/2009	14:04	CM
Sodium, Na - Dissolved	115.52	mg/L	EPA 200.7	0.090	12/10/2009	14:04	CM
Zinc, Zn - Dissolved	0.007	mg/L	EPA 200.7	0.004	12/10/2009	14:04	CM

Respectfully submitted,
SGS NORTH AMERICA INC.

Allen Huntington
Huntington Laboratory



APPENDIX C
DEPARTMENT OF COMMERCE
CERTIFICATES OF EXISTENCE



Utah Department of Commerce
Division of Corporations & Commercial Code
160 East 300 South, 2nd Floor, PO Box 146705
Salt Lake City, UT 84114-6705
Service Center: (801) 530-4849
Toll Free: (877) 526-3994 Utah Residents
Fax: (801) 530-6438
Web Site: <http://www.commerce.utah.gov>

03/12/2010
4911242-015003122010-1556738

CERTIFICATE OF EXISTENCE

Registration Number: 4911242-0150
Business Name: SUNNYSIDE COGENERATION ASSOCIATES
Registered Date: April 24, 2001
Entity Type: DBA
Current Status: Good Standing

The Division of Corporations and Commercial Code of the State of Utah, custodian of the records of business registrations, certifies that the business entity on this certificate is authorized to transact business and was duly registered under the laws of the State of Utah. The Division also certifies that this entity has paid all fees and penalties owed to this state; its most recent annual report has been filed by the Division (unless Delinquent); and, that Articles of Dissolution have not been filed.



Kathy Berg

Kathy Berg
Director
Division of Corporations and Commercial Code

[Search all of Utah.gov »](#)**Utah** Department of
Commerce

Business Entity Search

[Help](#)

Business Entity Search - Principals:

Name	Type	City	Status
SUNNYSIDE COGENERATION ASSOCIATES	DBA	Sunnyside	Active

Position	Name	Address	
Applicant	SUNNYSIDE HOLDINGS I, INC.	103 SPRINGER BUILDING	WILMINGTON DE 19810
Applicant	SUNNYSIDE II, LP	C/O CONTELLATION POWER	BALTIMORE MD 21202
Registered Agent	BRIAN W BURNETT	10 E SOUTH TEMPLE ST	Salt Lake City UT 84133

Additional Principals on file at Division of Corporations: N

[Back to search results](#)[Do Another Search](#)

Your experience is important to us. Please click the link below to provide feedback.

[Feedback Form](#)[Department of Commerce Home](#) | [Division of Corporations Home](#) | [Contact Us](#)[Utah.gov Home](#) | [Utah.gov Terms of Use](#) | [Utah.gov Privacy Policy](#) | [Utah.gov Accessibility Policy](#) | [Translate Utah.gov](#)
Copyright © 2010 State of Utah - All rights reserved.

[Search all of Utah.gov »](#)Utah Department of
Commerce

Business Entity Search

[Help](#)

Name	Type	City	Status
SUNNYSIDE COGENERATION ASSOCIATES	DBA	Sunnyside	Active
Business Name:	SUNNYSIDE COGENERATION ASSOCIATES		
Entity Number:	4911242-0150		
Registration Date:	04/24/2001		
State of Origin:			

Address

ONE POWER PLANT RD PO BOX 159
Sunnyside, UT 84539

Status

Status:	Active
Status Description:	Good Standing
This Status Date:	04/24/2001
Last Renewed:	02/25/2010
License Type:	DBA
Delinquent Date:	04/24/2013

Registered Agent

Registered Agent:	BRIAN W BURNETT
	[Search BES] [Search RPS]
Address Line 1:	10 E SOUTH TEMPLE ST
Address Line 2:	STE 900
City:	Salt Lake City
State:	UT
Zip:	84133

Additional Information

NAICS Code:	2211
NAICS Title:	2211-Electric Power Generation, Transmis
Qualified Alien - I-94 or:	
Qualified Alien - Registration No:	
U.S. Citizen - SSN or:	

With this information, you can...

Images are not available for DBA documents at this time.

Purchase Certificate of Existence

If you would like to purchase a Certificate of Existence for this business entity, select the button to the left. You will be assessed a **\$ 12.00 fee** for this service. You will need Adobe Reader to view this certificate. If you do not have Adobe Reader, click on the button below and download it.



Access Principal Information

If you would like to receive information on the principal individuals associated with this entity, click the button on the left. You will be assessed a **\$ 1.00 fee** for this information.

[Back to search results](#)[Do Another Search](#)[Department of Commerce Home](#) | [Division of Corporations Home](#) | [Contact Us](#)[Utah.gov Home](#) | [Utah.gov Terms of Use](#) | [Utah.gov Privacy Policy](#) | [Utah.gov Accessibility Policy](#) | [Translate Utah.gov](#)

Copyright © 2010 State of Utah - All rights reserved.



Utah Department of Commerce
Division of Corporations & Commercial Code
160 East 300 South, 2nd Floor, PO Box 146705
Salt Lake City, UT 84114-6705
Service Center: (801) 530-4849
Toll Free: (877) 526-3994 Utah Residents
Fax: (801) 530-6438
Web Site: <http://www.commerce.utah.gov>

03/12/2010
2113550-018103122010-1943911

CERTIFICATE OF EXISTENCE

Registration Number: 2113550-0181
Business Name: SUNNYSIDE II, L.P.
Registered Date: December 30, 1994
Entity Type: Limited Partnership - Foreign
Current Status: Good Standing

The Division of Corporations and Commercial Code of the State of Utah, custodian of the records of business registrations, certifies that the business entity on this certificate is authorized to transact business and was duly registered under the laws of the State of Utah. The Division also certifies that this entity has paid all fees and penalties owed to this state; its most recent annual report has been filed by the Division (unless Delinquent); and, that Articles of Dissolution have not been filed.



Kathy Berg

Kathy Berg
Director
Division of Corporations and Commercial Code

[Search all of Utah.gov »](#)**Utah** Department of
Commerce

Business Entity Search

[? Help](#)

Business Entity Search - Principals:

Name	Type	City	Status
SUNNYSIDE II, L.P.	Limited Partnership	BALTIMORE	Active

Position	Name	Address	
Registered Agent	C T CORPORATION SYSTEM	136 EAST SOUTH TEMPLE, SUITE 2100	Salt Lake City UT 84111
Partner	SUNNYSIDE II, INC.	750 E PRATT STREET 5TH FL	Baltimore MD 21202

Additional Principals on file at Division of Corporations: N

[Back to search results](#)[Do Another Search](#)

Your experience is important to us. Please click the link below to provide feedback.

[Feedback Form](#)[Department of Commerce Home](#) | [Division of Corporations Home](#) | [Contact Us](#)[Utah.gov Home](#) | [Utah.gov Terms of Use](#) | [Utah.gov Privacy Policy](#) | [Utah.gov Accessibility Policy](#) | [Translate Utah.gov](#)
Copyright © 2010 State of Utah - All rights reserved.



Search all of Utah.gov »

Utah Department of
Commerce

Business Entity Search

[? Help](#)

Name	Type	City	Status
SUNNYSIDE II, L.P.	Limited Partnership	BALTIMORE	Active
Business Name:	SUNNYSIDE II, L.P.		
Entity Number:	2113550-0181		
Registration Date:	12/30/1994		
State of Origin:	DE		

Address

750 E PRATT ST 17TH FLOOR
BALTIMORE, MD 21202

Status

Status:	Active
Status Description:	Good Standing
This Status Date:	N/A
Last Renewed:	11/25/2009
License Type:	Limited Partnership - Foreign
Delinquent Date:	12/30/2010

Registered Agent

Registered Agent:	C T CORPORATION SYSTEM
	[Search BES] [Search RPS]
Address Line 1:	136 EAST SOUTH TEMPLE, SUITE 2100
Address Line 2:	
City:	Salt Lake City
State:	UT
Zip:	84111

Additional Information

Additional Principals:	N
Amendment Date:	
NAICS Code:	5239
NAICS Title:	5239-Other Financial Investment Activiti
Qualified Alien - I-94 or:	
Qualified Alien - Registration No:	
U.S. Citizen - SSN or:	

With this information, you can...

If you would like to view images of paper filings for this business entity, select the button to the left. You will be assessed a **\$ 2.00** fee per image of a document for this service.

If you would like to purchase a Certificate of Existence for this business entity, select the button to the left. You will be assessed a **\$ 12.00** fee for this service. You will need Adobe Reader to view this certificate. If you do not have Adobe Reader, click on the button below and download it.



If you would like to receive information on the principal individuals associated with this entity, click the button on the left. You will be assessed a **\$ 1.00** fee for this information.

[Department of Commerce Home](#) | [Division of Corporations Home](#) | [Contact Us](#)
[Utah.gov Home](#) | [Utah.gov Terms of Use](#) | [Utah.gov Privacy Policy](#) | [Utah.gov Accessibility Policy](#) | [Translate Utah.gov](#)

Copyright © 2010 State of Utah - All rights reserved.



Utah Department of Commerce
Division of Corporations & Commercial Code
160 East 300 South, 2nd Floor, PO Box 146705
Salt Lake City, UT 84114-6705
Service Center: (801) 530-4849
Toll Free: (877) 526-3994 Utah Residents
Fax: (801) 530-6438
Web Site: <http://www.commerce.utah.gov>

03/12/2010
1215877-014303122010-2374070

CERTIFICATE OF EXISTENCE

Registration Number: 1215877-0143
Business Name: SUNNYSIDE HOLDINGS I, INC.
Registered Date: December 30, 1994
Entity Type: Corporation - Foreign - Profit
Current Status: Good Standing

The Division of Corporations and Commercial Code of the State of Utah, custodian of the records of business registrations, certifies that the business entity on this certificate is authorized to transact business and was duly registered under the laws of the State of Utah. The Division also certifies that this entity has paid all fees and penalties owed to this state; its most recent annual report has been filed by the Division (unless Delinquent); and, that Articles of Dissolution have not been filed.



Kathy Berg

Kathy Berg
Director
Division of Corporations and Commercial Code

[Search all of Utah.gov »](#)**Utah** Department of
Commerce

Business Entity Search

[? Help](#)

Business Entity Search - Principals:

Name	Type	City	Status
SUNNYSIDE HOLDINGS I, INC.	Corporation	WILMINGTON	Active
Position	Name	Address	
Registered Agent	C T CORPORATION SYSTEM	136 EAST SOUTH TEMPLE, SUITE 2100	Salt Lake City UT 84111
Director	WILLIS S MCLEESE	1105 N. MARKET ST.	WILMINGTON DE 19801
President	CHRIS L THOMPSON	1105 N. MARKET STREET	WILMINGTON DE 19801
President	CHRIS L THOMPSON	1105 N. MARKET STREET	WILMINGTON DE 19801

Additional Principals on file at Division of Corporations: N

[Back to search results](#)[Do Another Search](#)

Your experience is important to us. Please click the link below to provide feedback.

[Feedback Form](#)[Department of Commerce Home](#) | [Division of Corporations Home](#) | [Contact Us](#)[Utah.gov Home](#) | [Utah.gov Terms of Use](#) | [Utah.gov Privacy Policy](#) | [Utah.gov Accessibility Policy](#) | [Translate Utah.gov](#)
Copyright © 2010 State of Utah - All rights reserved.

[Search all of Utah.gov »](#)Utah Department of
Commerce

Business Entity Search

[Help](#)

Name	Type	City	Status
SUNNYSIDE HOLDINGS I, INC.	Corporation	WILMINGTON	Active
Business Name:	SUNNYSIDE HOLDINGS I, INC.		
Entity Number:	1215877-0143		
Registration Date:	12/30/1994		
State of Origin:	DE		

Address

1105 N. MARKET STREET SUITE 1300
WILMINGTON, DE 19801

Status

Status:	Active
Status Description:	Good Standing
This Status Date:	03/23/2006
Last Renewed:	11/19/2009
License Type:	Corporation - Foreign - Profit
Delinquent Date:	12/30/2010

Registered Agent

Registered Agent:	C T CORPORATION SYSTEM [Search BES] [Search RPS]
Address Line 1:	136 EAST SOUTH TEMPLE, SUITE 2100
Address Line 2:	
City:	Salt Lake City
State:	UT
Zip:	84111

Additional Information

Additional Principals:	N
NAICS Code:	5617
NAICS Title:	5617-Services to Buildings and Dwellings
Qualified Alien - I-94 or:	
Qualified Alien - Registration No:	
Stock Class 1 Amount:	0000000000
Stock Class 2 Amount:	0000000000
Stock Class 3 Amount:	0000000000
Stock Class 4 Amount:	0000000000
U.S. Citizen - SSN or:	

With this information, you can...

[Search for Images](#)

If you would like to view images of paper filings for this business entity, select the button to the left. You will be assessed a \$ 2.00 fee per image of a document for this service.

[Purchase Certificate of Existence](#)

If you would like to purchase a Certificate of Existence for this business entity, select the button to the left. You will be assessed a \$ 12.00 fee for this service. You will need Adobe Reader to view this certificate. If you do not have Adobe Reader, click on the button below and download it.

[Access Principal Information](#)

If you would like to receive information on the principal individuals associated with this entity, click the button on the left. You will be assessed a \$ 1.00 fee for this information.

[Back to search results](#)[Do Another Search](#)[Department of Commerce Home](#) | [Division of Corporations Home](#) | [Contact Us](#)[Utah.gov Home](#) | [Utah.gov Terms of Use](#) | [Utah.gov Privacy Policy](#) | [Utah.gov Accessibility Policy](#) | [Translate Utah.gov](#)
Copyright © 2010 State of Utah - All rights reserved.

**MINE
MAP**


**DEPT OF
COMMERCE**

**WATER
DATA**

**CLIMATE
DATA**

**CERTIFIED
REPORTS**

**ANNUAL
REPORT**



APPENDIX D MINE MAP

As required under R645-302-525-270